

## Chapter 1 Introduction to InSpec

Micro-Vu's InSpec metrology software provides powerful, on-screen measuring functions reaching well beyond the realm of a measuring digital readout. Integrating the software with video measuring stages and motion control, Micro-Vu has created truly powerful Measuring Centers™.

A Micro-Vu Measuring Center™ includes the following items:

- InSpec Metrology Software.
- Precision measuring stage.
- Motion control electronics.
- High-resolution CCD camera and image processing circuit board.
- Programmable profile, axial, and surface lighting.

### What is InSpec for Windows?

InSpec Metrology Software is a measuring application for vision measuring machines. It is an extremely powerful metrology tool, yet was designed to be easy to use and program. If you are familiar with other Windows applications, such as Word or Excel, you should find InSpec familiar and intuitive.

InSpec supports many types of geometric features and operations. A feature may be an edge, height, hole, radius, or one of many other geometric characteristics on a part. When a feature is measured, InSpec calculates the position, size, and form of the feature.

InSpec is easy to program. InSpec uses a "teach" style programming where a program is automatically written for you as you measure a part. These programs can be saved onto the computer hard drive or floppy disk. Programs can be opened and rerun later. With DXF, IGES, Gerber, and Excellon files, you can import features into InSpec and create programs even faster.

InSpec records measurements automatically. After measuring a part, you can browse through the measurement data and video tools used to capture the data. You can compute distances and construct new features from measured features. The data can be saved and used in spreadsheets or Statistical Process Control (SPC) software to track production trends.

InSpec measures features using a few or many data points. A minimum number of data points are required for each type of feature based on geometry. For example, a line requires a minimum of two points. It is simple to use additional points if desired. Just press the "more points" icon and enter additional points. Using additional points will yield greater accuracy and repeatability.

InSpec lets you construct features by bisecting, intersecting, or using the center locations of other features in a program. New features can be constructed from existing ones. When constructions have more than one solution, a construction dialog will appear to help you select the correct construction. With a line intersecting a circle there are two intersection points. InSpec would automatically display a dialog to help you select the correct point.

Easily set and align to datum features. Alignment functions include level, skew, and set origin. Leveling, skewing, and setting the origin define what is known as the part coordinate system. InSpec supports multiple coordinate systems giving the user the flexibility to set several zero points, alignments, or datum features in a single part program. In digital readout (DRO) terminology, this is analogous to having several absolute and incremental datum features on one part.

Add on-screen instructions for users. InSpec offers user prompts. Messages can be entered and will be displayed when a part is measured. Use the prompts to guide the user through the program or to request data from the user, such as the lot number, date, or operator ID number.

### The Measuring Machine

The stage is a precision electromechanical assembly that sends precise X, Y, and Z position data to

the measuring software. When the stage is moved, linear encoders output the incremental displacement to the computer.

**Three-Axis Measuring:** The part to be measured is placed or fixtured on the measuring stage and viewed by the camera from above. The measuring stage (or the camera above on some systems) moves so that the desired area of the part is in the camera view. Left to right motion is called the X-axis. Similarly, motion front to back is called the Y-axis. The camera moves up and down in the vertical, or Z-axis, in order to measure heights and to focus on the part. Because measurements can be taken in the X, Y, and Z-axes, we call this type of system a three-axis measuring machine.

**Stage Movement:** The stage and camera are moved using a joystick or the on-screen mouse control in the Camera Window. In general, for the X and Y-axes, pushing the joystick in a certain direction will move the part's image in the same direction on the video monitor. These directions can be reversed on some systems. The speed at which the stage moves is proportional to the deflection from center. If the joystick is pushed slightly, the stage will move slowly. There is no need to tap the joystick to jog slight amounts. For faster movement, press the "Rapid" button or the trigger button on Qubix / Quantum systems.

To control the camera or Z position, press and hold the top button on the joystick and move the joystick in the Y-axis direction. On systems with a Z button, press and hold the Z button and move the joystick in the Y-axis direction.

When controlling the stage using the mouse, simply click on the Stage Controller icon and drag in the direction you want to move. The speed will increase as you drag further and further from the icon.

## Vision Components

The vision components consist of a camera, frame grabber, and a set of software tools to find feature edges. Together they take care of looking at the part, capturing the image, and computing the edge location.

By combining a measuring stage with the vision components, parts can be measured accurately and automatically. This powerful yet easy-to-use system gives you automatic detection of edges, motorized part positioning, and sophisticated geometric measuring capability. A Micro-Vu Measuring Center™ complements any quality control area by adding sophisticated non-contact coordinate measurement capabilities.

### Key Features of Automated Vision

- Significantly improve inspection repeatability by eliminating operator subjectivity.
- Measure parts to sub-pixel accuracy.
- View large and small features with adjustable magnification.
- Automatically find edges of features on the surface of a part.
- Automatically determine profile edges on the part.
- Measure in the Z (vertical) axis by automatically focusing on the part.
- Enhance desired edges with programmable lighting.
- Position the motorized stage using the joystick or mouse.
- Intuitively create a part program as you measure a part the first time.
- Save and load part programs for an unlimited number of parts.
- Print reports of all measurements along with a diagram of the measured part.
- Export data to spreadsheets, SPC, or reports.

### Starting Up Your Measuring Center™

After the system has been properly installed, you will be able to run InSpec and take measurements. Turn on the computer.

*Notify **all users** that the computer should be turned on before the machine.*

Turn on the machine.

*The computer should already be powered up.*

Remove from the stage parts that may interfere with the stage volume initialization.

Double-click on the InSpec icon on the Desktop to open InSpec.

*Avoid using the zoom or joystick until after InSpec has completed the start up sequence.*

*If the Emergency Stop Switch is engaged when InSpec is started, a dialog box may indicate that the machine is halted. Disengage the Emergency Stop switch and click Recover and Continue.*

**NOTE FOR QUBIX AND QUANTUM MACHINES: Always turn the lower chassis off before shutting down Windows and turning off the computer. The lower chassis should not be on, unless the computer is on.**

### **Shutting Down Your Measuring Center™**

The machines are designed to run without interruption. Start with software when you are shutting down the system.

- Save your program if necessary.
- Close InSpec
- Turn off the machine.
- Shut down Windows and then the computer.

## **Technical Support**

If you have questions that are not answered in this manual, you should contact your local Micro-Vu Dealer. Your Micro-Vu Dealer is not only well versed with InSpec for Windows, but your local dealer may be familiar with your application and be able to solve your problem quickly.

You may also contact Micro-Vu directly for technical support.

PHONE: 707.838.6272

FAX: 707.838.3985

EMAIL: support@microvu.com


Regardless of whom you contact, you need to have the following information ready:

- Machine type, size, and serial number
- Software version and operating system
- Detailed information on the problem that you are experiencing

## Chapter 2 InSpec's User Interface

Combined with a number of pop-up windows and pull down menus, the layout provides an easy-to-understand yet powerful interface. This chapter will discuss four of the five sections of the interface. The Program section is discussed in the following chapter.

1. The Schematic Window displays a graphic representation of the part.
2. The Results section displays information about the current feature or a log of all measured features.
3. The Status Section displays the current stage position, units, and lighting settings.
4. The Camera Window displays the video image and vision tools and optional touch probe functions.
5. The Program Interface displays the current program list with the feature, construction, and tool icons.



### Schematic Window

InSpec draws a diagram of the programmed features in the top left section of the screen. Right click options and colors simplify identification and selection of features.

Within the schematic window you can use the mouse to select single or multiple features. Use Windows conventions such as holding the Control key down to select multiple features and click and drag to select features within a selection area.


Colors are used to help the user distinguish selected and toleranced features. Features are normally drawn using thin green lines. Thick green lines designate the “selected” feature(s). Magenta indicates that the mouse is currently hovering over the feature. Red indicates that the feature is incomplete or out of tolerance. Features that have playback disabled will appear light gray.

### Current Stage Position

Thin gray crosshairs indicate the current stage position relative to the displayed part. When you run a program, a second set of crosshairs is displayed showing the position of the next feature. This is especially helpful at the beginning of a program or when measuring manual points.

## Schematic Views

InSpec offers five standard views of the part schematic. Operators can choose between the isometric, XZ, YZ, XY, and PCS views.



The perspective view rotates the schematic for a view from above the front right corner of the stage.

The XZ, YZ, and XY views are relative to the machine coordinate system (MCS). As the icons depict, these show the front, right, and top view of the part as it lays on the stage. For example, the top view will show a tilted schematic of the part if the part is not aligned to the stage axis.

The part coordinate system (PCS) view shows the schematic relative to current coordinate system, which is the system of the current feature. Program may have many different origins, skews, and levels.

## Schematic Zoom

Customers use Micro-Vu systems to measure a variety of parts. Some larger parts have small features. InSpec provides zoom capabilities in the schematic so that you can view the relative position of these features.

Use the Fit, Zoom-In, and Zoom-Out icons directly below the schematic window to zoom in on smaller features and zoom out to see the entire schematic. When the schematic is in the "Zoom" state, a center click on the mouse wheel will allow the user to pan the schematic view. Another mouse click (left, right, or center) will exit the "Pan" mode.



Use the Zoom-In icon toggles between the "Zoom" state and the "Pick" state. When the button is pressed, the mouse cursor will show a magnifying glass when the mouse is in the schematic window. To zoom in on features, click-and-drag a window around the area you would like to enlarge.

When the button is "up", the mouse cursor will be an arrow allowing the user to select features.



The Zoom-Out icon incrementally decreases the zoom so that you can make slight increases to the field of view.



The Zoom-to-Fit icon will change the schematic zoom to display all of the features in the program and the location of the current stage position. Note that if the camera location is not near the part and the part is relatively small, then the part features will appear small on the screen.

## Tags



The Tags icon allows the user to mark selected features on the schematic. This makes it easier for the user to locate specific features. A feature's Tag displays the number or name of the feature. The user may select a group of features from the Features list and change the tag status for all of the selected features at one time. When a feature is renamed the feature's name is displayed in place of its number.

## Results Summary

InSpec displays measurement data by feature and as a summary of all features. The Feature View, Points View, and Log View are displayed at the top center of the screen. Use tabs at the top of the display to switch between the three views.

## Feature View

InSpec displays the name, system, measured values, and condition of tolerances for the current feature in the Feature View. Green check marks, red Xs, and yellow rulers indicate the status of the feature. A feature may be in tolerance or out of tolerance, or there may be a problem with a tool or with the measurement. Smaller green checks and red Xs will appear next to feature characteristics that are toleranced indicating that the individual characteristics are in or out of tolerance. The summary updates immediately when another feature is selected. The arrow on the right side of the Features List indicates which is the current feature.

The screenshot shows the 'Summary' tab of the InSpec interface. At the top, there are three tabs: 'Summary', 'Points', and 'Log'. Below the tabs, the 'Current Feature' is 'Circle Hole 4' (indicated by a green checkmark) and the 'Parent System' is 'System Part'. A table below lists various properties and their values:


Property	Actual	Out/Tol
Center X	16.14399	
Center Y	4.74344	
Center Z	0.00000	
Radius	0.35342	
Diameter	0.70684	
Circumference	2.22060	
Area	0.3924	
Circularity	0.01839	
RMS Residual Error	0.00517	
TP RFS	0.08896	
Date/Time	2007-07-09 16:13:32	

Many feature types have ten or more characteristics that may be displayed, toleranced, and exported. You can choose which characteristics are displayed for each feature type. Select Configure Summary from the Tools menu to customize the display of feature characteristics.

### Points View

When most features are measured in InSpec, the data points are used to create a feature with perfect geometry. The deviation of each of the individual data points from the perfect geometry of the feature is called its residual to the fit.

The Points View shows a graphical depiction of the residuals of all the data points of a feature. The errors can be exaggerated between 1x and 1000x by moving the slider bar along the top of the dialog. By hovering over any point in the Points View, its residual will be displayed. If you right click on a single point, there is a Move To Point option which will center the camera window on that particular point.




Some features, such as splines, go through each individual data point. These features have no

residuals to show in the Points View.

## Log View

The Log View summarizes the results of a program. There are three buttons on the Log View display, In Tolerance, Out of Tolerance, and Failed to Measure. Selecting and un-selecting these will customize the output in the Log View. Commonly, all the buttons are selected, or the Out of Tolerance and Failed to Measure are selected together.

When you click on a feature in the log view, it will become the active feature in the program list. When you hover with the mouse over a feature in the log view a tool tip will be displayed. The tool tip will include the feature summary characteristics and values. Characteristics that have been selected for export will be displayed to the right of the feature name.



If you right click on a feature in the Log View, it brings up the Feature Context Menu. The Feature Context Menu lets you remeasure or edit the properties of a feature or a group of features. For more details of the Feature Context Menu, please refer to Chapter 3.

## In Tolerance

Features that are in tolerance will be displayed with a green check mark next to them. Individual tolerances are listed below the feature.

Features without any tolerances are considered In Tolerance and will also be displayed. If any characteristics of the feature have been selected for export, the values will appear after the feature name.

## Out of Tolerance

Features that are Out of Tolerance will be displayed with a red X. A feature is considered Out of Tolerance if it has any characteristics that are out of tolerance. The actual and the deviation from tolerance values will be displayed below the feature name.

## Failed to Measure

Features that fail to measure will be displayed with a yellow and red ruler. If a tool fails in a feature, the feature cannot be measured, and hence, tolerances cannot be evaluated. InSpec will list the failed tools in the log view. When you click on a failed tool, InSpec will display the tool snapshot. The operator can now adjust the tool as needed for the tool to succeed.



## Lighting Control


The lighting is completely programmable. The intensity of each light calibration "channel" is saved to the program on an image-by-image basis. Each tool of each feature can have separate settings. The lights can be calibrated for each machine so that the light intensity of one machine can be duplicated on another machine – this allows for program swapping between machines.

If you are using 1280x1024 display resolution, the Lighting Control dialog will “dock” under the DRO. If you are using a lower display resolution, then the light bulb icon in the top left corner of the camera window is used to display and hide the Lighting Control dialog.

To change the lighting, select the **surface**, **coaxial**, or **profile** light by clicking on the appropriate area of the lighting dialog. Then adjust to the desired level using the slide on the right. After the first change in lighting, subsequent adjustments can be made with the center mouse wheel.

The **surface light** is produced with a ring of LEDs around the lens. The surface light can be controlled as one unit, by rings, octants or quadrants, or by individual sectors. Buttons at the bottom of the lighting display allow you to change between these settings. The slider on the right adjusts intensity of the selected channel. You may select a group of sectors by clicking on the sector and holding the Ctrl key or by click-and-dragging over the sectors.

Depending on the system, the surface light may have 1, 2 or 5 rings and 4, 16 or 40 programmable sectors respectively. Below are examples of the display for the Macro Light Ring.





The **profile light** originates below the part. It is the best light to use on through holes and the edges of parts. Using the profile light alone creates a black and white image with sharp, high contrast edges. Use the least amount of light needed to make the part appear black and the open area light gray. Using excessive amounts of light will make the light "bleed" over the edges. Holes and internal features will appear and measure larger and outer features and distances will appear and measure smaller.

The **coaxial light** originates at the side of the zoom lens, reflects off a split mirror in the zoom lens, and beams straight down on the part through the center of the lens. Axial light is useful at high magnification or for looking in blind holes and at features on flat surfaces.

**Lights Off** and **Auto Lights** icons are found in the lower right corner of the lighting dialog. These Auto Lights functions will set the selected lighting segments based on the image intensity and composition. The light setting will be appropriate for many but not necessarily all applications.

### Lighting Tips

Before you begin a new part measurement program, take some time to play with the lighting. Using well-illuminated edges will make a more reliable inspection program.

Using the 2X adapter shortens the working distance of the lens. This requires a 2X light ring because the it will be closer to the part. A 2X light ring appears brighter with lighting angles closer to horizontal that help enhance difficult edges and chamfers. Conversely, without the 2X, the working distance is longer; lighting appear slightly dimmer, and lighting angles are closer to vertical.

On **reflective parts**, turning off one or more of the quadrants of the ring light can often significantly reduce glare. For example, on a shiny horizontal edge, turning off the front and rear sections can often clean up the image.

For **deep edges** (like the sidewall of a part), it is sometimes useful to turn up the quadrant opposite the higher edge. This sometimes reflects light off the deeper section and sharpens up the edge.

For illuminating **deep holes**, many times the only lighting option is the axial or "through-the-lens" light. This will usually provide enough light to focus on the bottom of the hole to measure the depth of the hole.

For **profile edges**, it is usually better to turn off the surface and axial lights so that any glare and reflections from the part do not interfere with the edge detection.

**Beware of ambient light.** Being near a window or having lights directly above the machine will reduce the effectiveness of the programmable lighting.

### The Status Section

The top right section of the InSpec screen is dedicated to status settings, including position, units, and lighting.

The digital readout (DRO) appears in the top-right corner of the screen. This counter shows the X-Y-Z position or R-Theta-Z position of the crosshairs. The icons below the DRO allow the user to move the stage and specify the units of measurement.



### Displayed Units



The buttons below the DRO allow the user to specify the units and type of coordinate system. Units can be selected and saved with each program.

The first pair toggles the system between X-Y-Z and R-Theta-Z formats, Cartesian and Polar

formats. The next pair set the linear units, inches or millimeters. The next pair of buttons toggles angular values between decimal and degrees:minutes:seconds. The last two buttons toggle the temperature units.

## The Camera Window

The camera window contains an actual image of your part. It may display live video or snapshots depending on whether you are teaching or running a program. InSpec will display a diagram of the selected touch probe when the optional touch probe is in use. Use the icons along the top of the window to position the part view.



### Stage Control

Although a joystick is provided, the stage can be completely controlled from the mouse and keyboard. The X-Y movement is controlled with the icon on the four-directional icon. The Z movement is controlled with the two-directional icon. When you click and drag on one of the icons the stage will begin to move. The further the mouse is dragged the faster the movement.

It is recommended that you start slow and do not drag more than an inch from the icon until you become familiar with the control. Move slowly around parts and prevent contact between the camera and lighting and your parts and fixtures. Be especially careful when lowering the Z-axis.




### Auto Focus

This icon can be used to bring the image into focus. After getting the image roughly into focus (using the Z-axis control), click on the icon. The system will move in Z and focus on the part.

Higher magnifications will produce sharper, more repeatable focus. This is in part due to the fact that InSpec looks at the portion of the image inside the blue box at the center of the crosshairs. The pixel size of the box remains fixed. Low magnification effectively increases the area used to focus, and high magnification effectively uses a smaller area to focus. The larger area viewed at low magnification will encompass more Z variation of the surface. Hence, the focus data creates a wider bell curve with a less repeatable result.

Focus is based on the contrast of the image. Parts such as the chrome on glass screen calibration target are considered ideal with a little profile light. You will usually find that even on black, white, and uniformly gray parts, there is more than enough contrast to use the auto focus and the focus point tool.

Click with the left mouse button on the icon to initiate the automatic focus search.



### Change Zoom

Use this list box to select the zoom stop and zoom in and out on a part.

The values displayed are the on-screen magnification values. The magnification displayed is determined by the screen-calibration and the resolution and size of the monitor.

Click on the down-arrow to display a list of zoom stops. Select a zoom stop with the mouse, and the zoom will then adjust to the new value. After the first zoom change, subsequent adjustments can be made with the center wheel on the mouse.

The magnification is recorded with each vision tool when programming a part. When a program runs, the zoom lens repeats the settings that were taught.

### Digital Zoom

Depending on the type of machine, some of the highest zoom settings on your system may be digital zoom. Digital zoom is done via software (as opposed to moving lenses) and therefore happens instantaneously. If you change zoom setting and do not have to wait for the zoom motor to come to position, then you are changing between 2 digital zoom settings.

Digital zoom uses the camera image from the highest optical zoom setting, and enlarges a portion of that image to fill the camera window. It is useful for precisely placing vision tools on small features. It has been used to accurately measure 10 micron gaps and circles.

Digital zoom will add 3x magnification to your system. Therefore a 12x optical system becomes a 36x system and a 6.5x system becomes a 19.5x system. It does not, however, add optical resolution to the system.

### Camera Window Context Menu

A right-click with the mouse in the camera window will display the Camera Context Menu.



### Move Here


Short moves can be difficult to make, especially at high magnification. The "Move Here" function makes small moves very easy. After you right-click on a feature in the camera window and choose "Move To" InSpec will move the stage to center the image on the location that you clicked.

- Place the mouse cursor on a feature in the camera window.
- Right-click and select Move Here.

The Move Here feature is also a good way to test the Optics Calibration. If the selected feature is off center after the move, it may indicate that the screen calibration is incorrect. When you add or remove a 2x adapter without re-calibration of the optics, Move Here will overshoot or undershoot the selected feature. If the Move Here does not seem to reach the desired location, run the Optics Calibration under the Tools menu or consult your Micro-Vu distributor.

### Move To...

Clicking on the Move to... option will bring up the following dialog box:



In the Move to Coordinates pop-up window, the user can toggle between Move Relative and Move Absolute. The moves will use the units shown below the DRO.

Choosing Move Relative will move the stage the specified X, Y, & Z distances relative to the current stage position.

Choosing Move Absolute will move to the specified X-Y-Z coordinates with respect to the origin of the current coordinate system.

Enter the X, Y, Z (and W, if applicable) off-set distances or coordinates. The W axis is only displayed on systems equipped with the optional RSD-60 Rotary Indexer.

Before clicking "OK," check for possible collisions. The system will make a straight line move from the current position.

### **Show Crosshairs**

The blue crosshairs can be displayed or hidden. A check next to Show Crosshairs indicates that the crosshairs are currently visible. Toggle between visible and hidden by selecting Show Crosshairs from the menu.

### **Save Snapshot**

Save Snapshot captures the video image in the Camera Window to a file in BMP or JPG format. The image can be saved with or without the Vision Tool and crosshairs by checking or un-checking the Show Tool check box.

To save an image, right click on the video image in the Camera Window. From the listed options, select Save Snapshot. Select the file type (BMP or JPG) from the bottom of the Save As window, and select the directory and file name.


The entire InSpec interface can be captured using the PrintScr key. The Camera Window will be blank because of the live video display. If you need the interface and the camera window together, you can overlay them in most drawing programs.

## Chapter 3 The Program Interface

Information about your part program is displayed in the lower left corner of the screen. The features and inputs are listed on the left with the programming icons just to the right. This view will vary in appearance depending on monitor resolution.

### Features List

The Features list displays a list of the features in the program. Features are added to the list as you create them the first time. When a program is run, features will be measured in the order that the features appear in the list.



A feature is usually some entity on a part that can be measured. InSpec can measure several types of features including arcs, angles, circles, distances, ellipses, lines, o-rings, and points. Features are measured from data points, field of view tools, or constructed from other features. There are also text, prompt, command line, part separators, and temperature features.

A triangle on the right of the Features list indicates which is the “current feature.”

The “current selection” of features is highlighted.

Multiple features can be selected using the SHIFT and CTRL keys. Operations, such as deleting, setting tolerances, or copying, are applied to the current selection of features.

### Features Context Menu

Right clicking on a feature in the Features list will bring up the following menu:



This menu provides the following functions:

- Remeasure – Recapture data for the selected feature(s).
- Exports – Open an Exports dialog box to select export characteristics.
- Tolerances... – Open a Tolerance dialog to set tolerance values for the selected feature(s).
- Select All – Select all features in the program.
- Delete – Delete the selected feature(s).
- Rename ... – Change the name of the current feature.
- Translate ... – Copy or Move selected feature(s) in X, Y, and Z.
- Rotate... – Copy or Move selected feature(s) around the system origin.
- Mirror... – Copy or Move selected feature(s) across the X or Y-axis.
- Set System – Relate selected feature(s) to a different coordinate system.
- Store... – Name and Save a feature for use in other programs.
- Edit Solution... - Change some geometric constructions.
- Edit Text... - Change the content of a Text feature.
- Playback... - By enabling or disabling a feature, you can control whether it is measured the next time the program is run.
- Set/Clear Drive Point - Control the center location for capturing an image.
- Set Zoom/Lights – Changes the zoom and light settings for all selected features to the currently displayed zoom and lights settings.
- Insert Here – Place the insertion bar in front of the current feature.
- Insert at End – Place the insertion bar after the last feature.


### **Remeasure**

This command is useful to test a tool on an edge or verify that the position of a translated feature is correct without rerunning the entire program. If the feature precedes the first X-Y origin, the user will be prompted to manually remeasure. If the feature follows the first system, InSpec will move to and measure the feature automatically.

### **Exports**

InSpec allows you to select individual characteristics of each feature to be exported to a data file. You can select a single feature or a group of features when setting the characteristics to be exported.

The export dialog box is a “pin up” box that remains on the screen as you select other features and set exports. Use the “X” in the top right to close the dialog.



To open the Feature Exports dialog box, first select the desired features in either the schematic or the Features list. Right click on the features and select Exports from the context menu. The F4 hot key will also open up the Feature Exports dialog.

Check the boxes for the properties and options you want to use. When your selection includes multiple feature types, use the “Feature Type” drop down menu in the top left to select one feature type at a time.


- Export with Labels – This toggle allows the user to include labels with the exported data, such as “Circle 10: Diameter.”
- Export Nominals and Tolerances – This toggle will include tolerance values if available, for each of the selected properties.
- Property – These check boxes allow the user to specify which characteristics of the selected features are to be exported.
- Label – InSpec allows you to customize labels for exported data. If Export with Labels is checked, InSpec will include a label with the export data. If no label is entered, then a default label is created using the feature name and property. The label is in quotes to facilitate use in spreadsheet and SPC software, i.e. “Circle 1: Center X”.

### Tolerances

InSpec has the ability to tolerance linear, angular, form, and positional dimensions. Tolerances can be applied to a single feature or to multiple features.

For a single feature, the tolerance dialog box will display the available tolerances for the selected feature type, as well as nominal values and calculated deviations from tolerance.

For multiple features, the dialog will only display the available tolerances for the selected feature type. Nominal values will typically have question marks (???) indicating that the values for the the features are different. If a number appears in the nominal column, then all of the features have the same value, for example Z=0.



The tolerance dialog box is a “pin-up” box that remains on the screen as you select other features and set tolerances. Access the tolerance window through the Features Context Menu or by using the F3 hot key.

### Select All

This option can be used to pick all of the features in a program. You may want to use this so that you can immediately tolerance features or delete all features to start a new program.

### Delete

This is one of the most used features. When programming, you often find a better way to measure a feature or change you mind after selecting a feature type. When you use “delete,” InSpec assumes that you mean it and does not ask for confirmation.

### Rename

InSpec automatically names features with a number. The name can be changed to an alphanumeric phrase of up to 32 characters. The name is used in the program, summary, reports, and tags. No two features in the same program can have the same name. A dialog box will appear and allow you to enter your own name for the feature. The hot key for the rename dialog box is F2.



### Translate

The Translate function allows the user to apply a transformation to a feature or a group of features. First select the group of features and then select Translate from the Features Context Menu.






At the top of the Translate menu box, first select the reference system for the translation. The reference system will default to the parent system used by the feature directly above the 'Insert Here' line. The default reference system will not be appropriate for every case.

By checking the *Append copy number to feature names* box InSpec will add *\_#* to the end of each feature name (including the source feature). For example, when feature *Diameter* is translated two times along the X axis the result is *Diameter\_1*, *Diameter\_2*, and *Diameter\_3*:



And if all 3 are translated again along the Y axis the result is a grid where all of the feature names correspond to their relative position:



The *Copies inherit last system of preceding block* checkbox is used to translate a section of features such that each copy will be relative to the preceding copy (as opposed to each copy being relative to the system chosen in the dialog).

This can be particularly useful when making copies to track a curve or surface with unknown geometry such as the free form of a flexible piece of plastic. For example, if you translate the following group of three features relative to system PCS




it will create point 13, system 14, and point 15. The parent system for point 15 will always be

system 14, however the parent system for features 13 and 14 will either be PCS (if the *Copies inherit last system of preceding block* is not checked) or will be system 11 (if the *Copies inherit last system of preceding block* is checked).

### Linear


A linear translation command will move or copy the selected features.



After selecting the proper system, enter the values for the translation. You have the choice of making copies which will be separated by the given translation interval, or moving the selected features. The selected features will be copied or moved when you click on OK. Remember that these features have not been measured. It is often helpful to test the locations of copied features. You can select one of the features and use the Remeasure command to verify that the tool position is correct.

### Grid


The Grid tab allows for features to be translated along 2 different axes with a single step.



The option to Move first in X or Y will effect the numbering of the features created. The *Append copy number to feature names* option is useful to automatically create feature names that correspond to positions in the grid.

### Table

The Table tab provides the functionality of being able to create features or blocks of features in a pattern that is not defined by standard geometric shapes.



With this option, it is possible to copy and paste values from a spreadsheet into InSpec and create features at those locations.

### Rotate

The Rotate command in the Features Context Menu allows the user to rotate a feature or multiple features in a program around the current system origin. This simplifies the programming of gear teeth, bolt hole patterns and other symmetric arrangements of features. To transform multiple features, select the group of features and then select Rotate from the Features Context Menu. Enter the angle of rotation and whether to move the original features or create a number of copies.



Checking *Append copy number to feature names* will add # to the end of each feature name (including the source feature). For example, when *BoltHoleCircle* is rotated to create 3 copies, the result will be *BoltHoleCircle\_1*, *BoltHoleCircle\_2*, *BoltHoleCircle\_3*, and *BoltHoleCircle\_4*.

### Mirror

The Mirror command in the Features Context Menu allows the user to flip a feature or multiple features in a program across the X or Y-axis. This simplifies the programming of symmetric features. In the Mirror dialog box, select the axis to mirror across and whether to move the original features or create a copy.



The *Append copy number to feature names* check box will add *\_#* to the end of each feature (including the source feature). For example, the result of making a mirrored copy of *Line4* would change the original feature to *Line4\_1* and create *Line4\_2*.

### Set System

Set System gives the user flexibility for taking measurements relative to different coordinate systems. Users will find that although they wrote a program to measure a feature relative to one coordinate system, they may want to know the location relative to a different system or to second system.

### Store Feature

InSpec software allows features to be stored in memory, so you can use them in other programs.

Storing a Feature is simple. First, Create a feature. Then choose *Store* from the Features Context Menu (right click on the feature name). The following dialog will appear:




Check the box next to *Store As* and enter a unique name. By checking the *Store Permanently* box you will save the feature permanently. If you do not check the box, the feature will be saved only for the current session of InSpec and will be deleted when InSpec is closed.

Fixtures are often used to position parts on the stage. By storing and using the location of a fixture, part programs can run completely automated without operator input. All the operator has to do is load the part and click on the Run icon.

First make a short program that creates a system origin and skew on the fixture. Store the system. Then begin the part program with a system that “Recalls” the stored feature. When you run the part program, InSpec will know where the part is supposed to be and can begin measuring without any user input.

### Edit Solution

There are a number of constructions that have multiple solutions. For instance a line may intersect with a circle in two locations. When you program a part a dialog box will pop up and allow you to select the correct solution. However if the wrong solution was selected, the Edit Solution option can be used to view and select the correct construction. The bold crosshairs shows the selected construction point.



### Edit Text

This option will allow you to edit existing text in a Text and Prompt type features. The dialog will give you the options to accept, reset, and cancel any changes.

This feature is convenient for exporting text to a data file, especially for cases where the text does not change very often. For instance, if you measured twenty samples per lot, the text message may say "LOT #7909." This could be exported with the data. For the next lot of twenty samples, you could Edit Text to change the number. This would be more convenient than using a Prompt feature that requires user input for each run.

### Playback

The playback setting can either be set to enabled or disabled. By default it is set as enabled, which means that when the program is run again, the feature will be measured. When the playback is set to disabled, the feature will become light gray in the schematic, and will not be measured next time the program is run.

A disabled feature will not appear in the Log View. If another feature is dependent on a playback-disabled feature, it will not measure either. You should not use playback-disabled features to define systems, or as constructions.

A disabled feature can be useful if the programmer would like to reference an outline of the part in the schematic, but does not actually want to measure the outline each time the program is run.

### Set / Clear Drive Point

Drive Points can be used to reduce measurement time or for special lighting.

Normally InSpec drives to the center of a tool and "grabs" an image.

Drive points allow the user to define the X-Y-Z location of the "grab" for a feature.

If a three by three array of holes fit in the field of view, you could position the stage on the center hole, select the nine diameters, and then set the drive point. During the run of the program, InSpec will take a single snapshot and use it to take measurements of all nine holes.

Likewise if the four sides of a small rectangle fit in the field of view, drive to the center, measure the four sides with F-Scan Line tools, and set the drive point for the rectangle. Then move on to the next feature.

If lighting is better with a feature off-center, use the drive point to lock the X-Y-Z position of the image grab.

### Set Zoom/Lights


The lighting and zoom settings are important for a program to run consistently from one part to the next. It may be helpful to raise the lighting or to decrease the zoom setting to make a program more reliable. When you use Set Zoom/Lights, InSpec will change the zoom and lights settings of the selected features to the current zoom and lights settings.

### Insert Here / Insert at End

The Insert features allow you to add features or copy features to rearrange the order that the features are measured. The insertion bar will be placed above the selected feature when you choose Insert Here, or at the end of the list when you select Insert at End.

### Inputs List

The Inputs list, located below the Features list, displays the individual components used to create the current feature. These entries tell how a feature was measured, whether vision tools or other features were used for data points. Inputs can be selected, edited, and deleted individually.



### Inputs Context Menu

Right clicking on an Input brings up the following menu:



This menu lets you do the following to the Input:


- **Move Here** – Drives the stage to where the Input was measured. This is available when vision tools are used as Inputs.
- **Edit Prompt...** – Displays a dialog box where you add and edit a prompt for the selected Input. The prompts usually are used to instruct the operator where to place the current tool. These are typically used at the beginning of a program or for manual points. If the Input is measured automatically, the prompt will only appear briefly on the screen.
- **Pick Section** – Allows editing of splines that have been used as inputs
- **Delete** – Allows deletion of the current Input.

## Chapter 3 The Program Interface

Information about your part program is displayed in the lower left corner of the screen. The features and inputs are listed on the left with the programming icons just to the right. This view will vary in appearance depending on monitor resolution.

### Features List

The Features list displays a list of the features in the program. Features are added to the list as you create them the first time. When a program is run, features will be measured in the order that the features appear in the list.



A feature is usually some entity on a part that can be measured. InSpec can measure several types of features including arcs, angles, circles, distances, ellipses, lines, o-rings, and points. Features are measured from data points, field of view tools, or constructed from other features. There are also text, prompt, command line, part separators, and temperature features.

A triangle on the right of the Features list indicates which is the “current feature.”

The “current selection” of features is highlighted.

Multiple features can be selected using the SHIFT and CTRL keys. Operations, such as deleting, setting tolerances, or copying, are applied to the current selection of features.

### Features Context Menu

Right clicking on a feature in the Features list will bring up the following menu:



This menu provides the following functions:

- Remeasure – Recapture data for the selected feature(s).
- Exports – Open an Exports dialog box to select export characteristics.
- Tolerances... – Open a Tolerance dialog to set tolerance values for the selected feature(s).
- Select All – Select all features in the program.
- Delete – Delete the selected feature(s).
- Rename ... – Change the name of the current feature.
- Translate ... – Copy or Move selected feature(s) in X, Y, and Z.
- Rotate... – Copy or Move selected feature(s) around the system origin.
- Mirror... – Copy or Move selected feature(s) across the X or Y-axis.
- Set System – Relate selected feature(s) to a different coordinate system.
- Store... – Name and Save a feature for use in other programs.
- Edit Solution... - Change some geometric constructions.
- Edit Text... - Change the content of a Text feature.
- Playback... - By enabling or disabling a feature, you can control whether it is measured the next time the program is run.
- Set/Clear Drive Point - Control the center location for capturing an image.
- Set Zoom/Lights – Changes the zoom and light settings for all selected features to the currently displayed zoom and lights settings.
- Insert Here – Place the insertion bar in front of the current feature.
- Insert at End – Place the insertion bar after the last feature.

### **Remeasure**


This command is useful to test a tool on an edge or verify that the position of a translated feature is correct without rerunning the entire program. If the feature precedes the first X-Y origin, the user will be prompted to manually remeasure. If the feature follows the first system, InSpec will move to and measure the feature automatically.

### **Exports**

InSpec allows you to select individual characteristics of each feature to be exported to a data file. You can select a single feature or a group of features when setting the characteristics to be exported.

The export dialog box is a “pin up” box that remains on the screen as you select other features and set exports. Use the “X” in the top right to close the dialog.





To open the Feature Exports dialog box, first select the desired features in either the schematic or the Features list. Right click on the features and select Exports from the context menu. The F4 hot key will also open up the Feature Exports dialog.

Check the boxes for the properties and options you want to use. When your selection includes multiple feature types, use the “Feature Type” drop down menu in the top left to select one feature type at a time.


- Export with Labels – This toggle allows the user to include labels with the exported data, such as “Circle 10: Diameter.”
- Export Nominals and Tolerances – This toggle will include tolerance values if available, for each of the selected properties.
- Property – These check boxes allow the user to specify which characteristics of the selected features are to be exported.
- Label – InSpec allows you to customize labels for exported data. If Export with Labels is checked, InSpec will include a label with the export data. If no label is entered, then a default label is created using the feature name and property. The label is in quotes to facilitate use in spreadsheet and SPC software, i.e. “Circle 1: Center X”.

### Tolerances

InSpec has the ability to tolerance linear, angular, form, and positional dimensions. Tolerances can be applied to a single feature or to multiple features.

For a single feature, the tolerance dialog box will display the available tolerances for the selected feature type, as well as nominal values and calculated deviations from tolerance.

For multiple features, the dialog will only display the available tolerances for the selected feature type. Nominal values will typically have question marks (???) indicating that the values for the the features are different. If a number appears in the nominal column, then all of the features have the same value, for example Z=0.



The tolerance dialog box is a “pin-up” box that remains on the screen as you select other features and set tolerances. Access the tolerance window through the Features Context Menu or by using the F3 hot key.

### Select All

This option can be used to pick all of the features in a program. You may want to use this so that you can immediately tolerance features or delete all features to start a new program.

### Delete

This is one of the most used features. When programming, you often find a better way to measure a feature or change you mind after selecting a feature type. When you use “delete,” InSpec assumes that you mean it and does not ask for confirmation.

### Rename

InSpec automatically names features with a number. The name can be changed to an alphanumeric phrase of up to 32 characters. The name is used in the program, summary, reports, and tags. No two features in the same program can have the same name. A dialog box will appear and allow you to enter your own name for the feature. The hot key for the rename dialog box is F2.



### Translate

The Translate function allows the user to apply a transformation to a feature or a group of features. First select the group of features and then select Translate from the Features Context Menu.




At the top of the Translate menu box, first select the reference system for the translation. The reference system will default to the parent system used by the feature directly above the 'Insert Here' line. The default reference system will not be appropriate for every case.

By checking the *Append copy number to feature names* box InSpec will add *\_#* to the end of each feature name (including the source feature). For example, when feature *Diameter* is translated two times along the X axis the result is *Diameter\_1*, *Diameter\_2*, and *Diameter\_3*:



And if all 3 are translated again along the Y axis the result is a grid where all of the feature names correspond to their relative position:



The *Copies inherit last system of preceding block* checkbox is used to translate a section of features such that each copy will be relative to the preceding copy (as opposed to each copy being relative to the system chosen in the dialog).

This can be particularly useful when making copies to track a curve or surface with unknown geometry such as the free form of a flexible piece of plastic. For example, if you translate the following group of three features relative to system PCS



it will create point 13, system 14, and point 15. The parent system for point 15 will always be

system 14, however the parent system for features 13 and 14 will either be PCS (if the *Copies inherit last system of preceding block* is not checked) or will be system 11 (if the *Copies inherit last system of preceding block* is checked).

### Linear


A linear translation command will move or copy the selected features.



After selecting the proper system, enter the values for the translation. You have the choice of making copies which will be separated by the given translation interval, or moving the selected features. The selected features will be copied or moved when you click on OK. Remember that these features have not been measured. It is often helpful to test the locations of copied features. You can select one of the features and use the Remeasure command to verify that the tool position is correct.

### Grid


The Grid tab allows for features to be translated along 2 different axes with a single step.



The option to Move first in X or Y will effect the numbering of the features created. The *Append copy number to feature names* option is useful to automatically create feature names that correspond to positions in the grid.

### Table

The Table tab provides the functionality of being able to create features or blocks of features in a pattern that is not defined by standard geometric shapes.



With this option, it is possible to copy and paste values from a spreadsheet into InSpec and create features at those locations.

### Rotate

The Rotate command in the Features Context Menu allows the user to rotate a feature or multiple features in a program around the current system origin. This simplifies the programming of gear teeth, bolt hole patterns and other symmetric arrangements of features. To transform multiple features, select the group of features and then select Rotate from the Features Context Menu. Enter the angle of rotation and whether to move the original features or create a number of copies.



Checking *Append copy number to feature names* will add # to the end of each feature name (including the source feature). For example, when *BoltHoleCircle* is rotated to create 3 copies, the result will be *BoltHoleCircle\_1*, *BoltHoleCircle\_2*, *BoltHoleCircle\_3*, and *BoltHoleCircle\_4*.

### Mirror

The Mirror command in the Features Context Menu allows the user to flip a feature or multiple features in a program across the X or Y-axis. This simplifies the programming of symmetric features. In the Mirror dialog box, select the axis to mirror across and whether to move the original features or create a copy.



The *Append copy number to feature names* check box will add *\_#* to the end of each feature (including the source feature). For example, the result of making a mirrored copy of *Line4* would change the original feature to *Line4\_1* and create *Line4\_2*.

### Set System

Set System gives the user flexibility for taking measurements relative to different coordinate systems. Users will find that although they wrote a program to measure a feature relative to one coordinate system, they may want to know the location relative to a different system or to second system.

### Store Feature

InSpec software allows features to be stored in memory, so you can use them in other programs.

Storing a Feature is simple. First, Create a feature. Then choose *Store* from the Features Context Menu (right click on the feature name). The following dialog will appear:




Check the box next to *Store As* and enter a unique name. By checking the *Store Permanently* box you will save the feature permanently. If you do not check the box, the feature will be saved only for the current session of InSpec and will be deleted when InSpec is closed.

Fixtures are often used to position parts on the stage. By storing and using the location of a fixture, part programs can run completely automated without operator input. All the operator has to do is load the part and click on the Run icon.

First make a short program that creates a system origin and skew on the fixture. Store the system. Then begin the part program with a system that “Recalls” the stored feature. When you run the part program, InSpec will know where the part is supposed to be and can begin measuring without any user input.

### Edit Solution

There are a number of constructions that have multiple solutions. For instance a line may intersect with a circle in two locations. When you program a part a dialog box will pop up and allow you to select the correct solution. However if the wrong solution was selected, the Edit Solution option can be used to view and select the correct construction. The bold crosshairs shows the selected construction point.



### Edit Text

This option will allow you to edit existing text in a Text and Prompt type features. The dialog will give you the options to accept, reset, and cancel any changes.

This feature is convenient for exporting text to a data file, especially for cases where the text does not change very often. For instance, if you measured twenty samples per lot, the text message may say "LOT #7909." This could be exported with the data. For the next lot of twenty samples, you could Edit Text to change the number. This would be more convenient than using a Prompt feature that requires user input for each run.

### Playback

The playback setting can either be set to enabled or disabled. By default it is set as enabled, which means that when the program is run again, the feature will be measured. When the playback is set to disabled, the feature will become light gray in the schematic, and will not be measured next time the program is run.

A disabled feature will not appear in the Log View. If another feature is dependent on a playback-disabled feature, it will not measure either. You should not use playback-disabled features to define systems, or as constructions.

A disabled feature can be useful if the programmer would like to reference an outline of the part in the schematic, but does not actually want to measure the outline each time the program is run.

### Set / Clear Drive Point

Drive Points can be used to reduce measurement time or for special lighting.

Normally InSpec drives to the center of a tool and "grabs" an image.

Drive points allow the user to define the X-Y-Z location of the "grab" for a feature.

If a three by three array of holes fit in the field of view, you could position the stage on the center hole, select the nine diameters, and then set the drive point. During the run of the program, InSpec will take a single snapshot and use it to take measurements of all nine holes.

Likewise if the four sides of a small rectangle fit in the field of view, drive to the center, measure the four sides with F-Scan Line tools, and set the drive point for the rectangle. Then move on to the next feature.

If lighting is better with a feature off-center, use the drive point to lock the X-Y-Z position of the image grab.

### Set Zoom/Lights


The lighting and zoom settings are important for a program to run consistently from one part to the next. It may be helpful to raise the lighting or to decrease the zoom setting to make a program more reliable. When you use Set Zoom/Lights, InSpec will change the zoom and lights settings of the selected features to the current zoom and lights settings.

### Insert Here / Insert at End

The Insert features allow you to add features or copy features to rearrange the order that the features are measured. The insertion bar will be placed above the selected feature when you choose Insert Here, or at the end of the list when you select Insert at End.


### Inputs List

The Inputs list, located below the Features list, displays the individual components used to create the current feature. These entries tell how a feature was measured, whether vision tools or other features were used for data points. Inputs can be selected, edited, and deleted individually.



### Inputs Context Menu

Right clicking on an Input brings up the following menu:



This menu lets you do the following to the Input:

- Move Here – Drives the stage to where the Input was measured. This is available when vision tools are used as Inputs.
- Edit Prompt... – Displays a dialog box where you add and edit a prompt for the selected Input. The prompts usually are used to instruct the operator where to place the current tool. These are typically used at the beginning of a program or for manual points. If the Input is measured automatically, the prompt will only appear briefly on the screen.
- Pick Section – Allows editing of splines that have been used as inputs
- Delete – Allows deletion of the current Input.




## Chapter 3 The Program Interface

Information about your part program is displayed in the lower left corner of the screen. The features and inputs are listed on the left with the programming icons just to the right. This view will vary in appearance depending on monitor resolution.

### Features List

The Features list displays a list of the features in the program. Features are added to the list as you create them the first time. When a program is run, features will be measured in the order that the features appear in the list.



A feature is usually some entity on a part that can be measured. InSpec can measure several types of features including arcs, angles, circles, distances, ellipses, lines, o-rings, and points. Features are measured from data points, field of view tools, or constructed from other features. There are also text, prompt, command line, part separators, and temperature features.

A triangle on the right of the Features list indicates which is the “current feature.”

The “current selection” of features is highlighted.

Multiple features can be selected using the SHIFT and CTRL keys. Operations, such as deleting, setting tolerances, or copying, are applied to the current selection of features.

### Features Context Menu

Right clicking on a feature in the Features list will bring up the following menu:



This menu provides the following functions:

- Remeasure – Recapture data for the selected feature(s).
- Exports – Open an Exports dialog box to select export characteristics.
- Tolerances... – Open a Tolerance dialog to set tolerance values for the selected feature(s).
- Select All – Select all features in the program.
- Delete – Delete the selected feature(s).
- Rename ... – Change the name of the current feature.
- Translate ... – Copy or Move selected feature(s) in X, Y, and Z.
- Rotate... – Copy or Move selected feature(s) around the system origin.
- Mirror... – Copy or Move selected feature(s) across the X or Y-axis.
- Set System – Relate selected feature(s) to a different coordinate system.
- Store... – Name and Save a feature for use in other programs.
- Edit Solution... - Change some geometric constructions.
- Edit Text... - Change the content of a Text feature.
- Playback... - By enabling or disabling a feature, you can control whether it is measured the next time the program is run.
- Set/Clear Drive Point - Control the center location for capturing an image.
- Set Zoom/Lights – Changes the zoom and light settings for all selected features to the currently displayed zoom and lights settings.
- Insert Here – Place the insertion bar in front of the current feature.
- Insert at End – Place the insertion bar after the last feature.


### **Remeasure**

This command is useful to test a tool on an edge or verify that the position of a translated feature is correct without rerunning the entire program. If the feature precedes the first X-Y origin, the user will be prompted to manually remeasure. If the feature follows the first system, InSpec will move to and measure the feature automatically.

### **Exports**

InSpec allows you to select individual characteristics of each feature to be exported to a data file. You can select a single feature or a group of features when setting the characteristics to be exported.

The export dialog box is a “pin up” box that remains on the screen as you select other features and set exports. Use the “X” in the top right to close the dialog.



To open the Feature Exports dialog box, first select the desired features in either the schematic or the Features list. Right click on the features and select Exports from the context menu. The F4 hot key will also open up the Feature Exports dialog.

Check the boxes for the properties and options you want to use. When your selection includes multiple feature types, use the “Feature Type” drop down menu in the top left to select one feature type at a time.


- Export with Labels – This toggle allows the user to include labels with the exported data, such as “Circle 10: Diameter.”
- Export Nominals and Tolerances – This toggle will include tolerance values if available, for each of the selected properties.
- Property – These check boxes allow the user to specify which characteristics of the selected features are to be exported.
- Label – InSpec allows you to customize labels for exported data. If Export with Labels is checked, InSpec will include a label with the export data. If no label is entered, then a default label is created using the feature name and property. The label is in quotes to facilitate use in spreadsheet and SPC software, i.e. “Circle 1: Center X”.

### Tolerances

InSpec has the ability to tolerance linear, angular, form, and positional dimensions. Tolerances can be applied to a single feature or to multiple features.

For a single feature, the tolerance dialog box will display the available tolerances for the selected feature type, as well as nominal values and calculated deviations from tolerance.

For multiple features, the dialog will only display the available tolerances for the selected feature type. Nominal values will typically have question marks (???) indicating that the values for the the features are different. If a number appears in the nominal column, then all of the features have the same value, for example Z=0.



The tolerance dialog box is a “pin-up” box that remains on the screen as you select other features and set tolerances. Access the tolerance window through the Features Context Menu or by using the F3 hot key.

### Select All

This option can be used to pick all of the features in a program. You may want to use this so that you can immediately tolerance features or delete all features to start a new program.

### Delete

This is one of the most used features. When programming, you often find a better way to measure a feature or change you mind after selecting a feature type. When you use “delete,” InSpec assumes that you mean it and does not ask for confirmation.


### Rename

InSpec automatically names features with a number. The name can be changed to an alphanumeric phrase of up to 32 characters. The name is used in the program, summary, reports, and tags. No two features in the same program can have the same name. A dialog box will appear and allow you to enter your own name for the feature. The hot key for the rename dialog box is F2.



### Translate

The Translate function allows the user to apply a transformation to a feature or a group of features. First select the group of features and then select Translate from the Features Context Menu.




At the top of the Translate menu box, first select the reference system for the translation. The reference system will default to the parent system used by the feature directly above the 'Insert Here' line. The default reference system will not be appropriate for every case.

By checking the *Append copy number to feature names* box InSpec will add *\_#* to the end of each feature name (including the source feature). For example, when feature *Diameter* is translated two times along the X axis the result is *Diameter\_1*, *Diameter\_2*, and *Diameter\_3*:



And if all 3 are translated again along the Y axis the result is a grid where all of the feature names correspond to their relative position:



The *Copies inherit last system of preceding block* checkbox is used to translate a section of features such that each copy will be relative to the preceding copy (as opposed to each copy being relative to the system chosen in the dialog).

This can be particularly useful when making copies to track a curve or surface with unknown geometry such as the free form of a flexible piece of plastic. For example, if you translate the following group of three features relative to system PCS




it will create point 13, system 14, and point 15. The parent system for point 15 will always be

system 14, however the parent system for features 13 and 14 will either be PCS (if the *Copies inherit last system of preceding block* is not checked) or will be system 11 (if the *Copies inherit last system of preceding block* is checked).

### Linear

A linear translation command will move or copy the selected features.



After selecting the proper system, enter the values for the translation. You have the choice of making copies which will be separated by the given translation interval, or moving the selected features. The selected features will be copied or moved when you click on OK. Remember that these features have not been measured. It is often helpful to test the locations of copied features. You can select one of the features and use the Remeasure command to verify that the tool position is correct.

### Grid


The Grid tab allows for features to be translated along 2 different axes with a single step.



The option to Move first in X or Y will effect the numbering of the features created. The *Append copy number to feature names* option is useful to automatically create feature names that correspond to positions in the grid.

### Table

The Table tab provides the functionality of being able to create features or blocks of features in a pattern that is not defined by standard geometric shapes.



With this option, it is possible to copy and paste values from a spreadsheet into InSpec and create features at those locations.

### Rotate

The Rotate command in the Features Context Menu allows the user to rotate a feature or multiple features in a program around the current system origin. This simplifies the programming of gear teeth, bolt hole patterns and other symmetric arrangements of features. To transform multiple features, select the group of features and then select Rotate from the Features Context Menu. Enter the angle of rotation and whether to move the original features or create a number of copies.



Checking *Append copy number to feature names* will add # to the end of each feature name (including the source feature). For example, when *BoltHoleCircle* is rotated to create 3 copies, the result will be *BoltHoleCircle\_1*, *BoltHoleCircle\_2*, *BoltHoleCircle\_3*, and *BoltHoleCircle\_4*.

### Mirror

The Mirror command in the Features Context Menu allows the user to flip a feature or multiple features in a program across the X or Y-axis. This simplifies the programming of symmetric features. In the Mirror dialog box, select the axis to mirror across and whether to move the original features or create a copy.



The *Append copy number to feature names* check box will add *\_#* to the end of each feature (including the source feature). For example, the result of making a mirrored copy of *Line4* would change the original feature to *Line4\_1* and create *Line4\_2*.

### Set System

Set System gives the user flexibility for taking measurements relative to different coordinate systems. Users will find that although they wrote a program to measure a feature relative to one coordinate system, they may want to know the location relative to a different system or to second system.

### Store Feature

InSpec software allows features to be stored in memory, so you can use them in other programs.

Storing a Feature is simple. First, Create a feature. Then choose *Store* from the Features Context Menu (right click on the feature name). The following dialog will appear:




Check the box next to *Store As* and enter a unique name. By checking the *Store Permanently* box you will save the feature permanently. If you do not check the box, the feature will be saved only for the current session of InSpec and will be deleted when InSpec is closed.

Fixtures are often used to position parts on the stage. By storing and using the location of a fixture, part programs can run completely automated without operator input. All the operator has to do is load the part and click on the Run icon.

First make a short program that creates a system origin and skew on the fixture. Store the system. Then begin the part program with a system that "Recalls" the stored feature. When you run the part program, InSpec will know where the part is supposed to be and can begin measuring without any user input.

### Edit Solution

There are a number of constructions that have multiple solutions. For instance a line may intersect with a circle in two locations. When you program a part a dialog box will pop up and allow you to select the correct solution. However if the wrong solution was selected, the Edit Solution option can be used to view and select the correct construction. The bold crosshairs shows the selected construction point.



### Edit Text

This option will allow you to edit existing text in a Text and Prompt type features. The dialog will give you the options to accept, reset, and cancel any changes.



This feature is convenient for exporting text to a data file, especially for cases where the text does not change very often. For instance, if you measured twenty samples per lot, the text message may say "LOT #7909." This could be exported with the data. For the next lot of twenty samples, you could Edit Text to change the number. This would be more convenient than using a Prompt feature that requires user input for each run.

### Playback

The playback setting can either be set to enabled or disabled. By default it is set as enabled, which means that when the program is run again, the feature will be measured. When the playback is set to disabled, the feature will become light gray in the schematic, and will not be measured next time the program is run.

A disabled feature will not appear in the Log View. If another feature is dependent on a playback-disabled feature, it will not measure either. You should not use playback-disabled features to define systems, or as constructions.

A disabled feature can be useful if the programmer would like to reference an outline of the part in the schematic, but does not actually want to measure the outline each time the program is run.

### Set / Clear Drive Point

Drive Points can be used to reduce measurement time or for special lighting.

Normally InSpec drives to the center of a tool and "grabs" an image.

Drive points allow the user to define the X-Y-Z location of the "grab" for a feature.

If a three by three array of holes fit in the field of view, you could position the stage on the center hole, select the nine diameters, and then set the drive point. During the run of the program, InSpec will take a single snapshot and use it to take measurements of all nine holes.

Likewise if the four sides of a small rectangle fit in the field of view, drive to the center, measure the four sides with F-Scan Line tools, and set the drive point for the rectangle. Then move on to the next feature.

If lighting is better with a feature off-center, use the drive point to lock the X-Y-Z position of the image grab.

### Set Zoom/Lights


The lighting and zoom settings are important for a program to run consistently from one part to the next. It may be helpful to raise the lighting or to decrease the zoom setting to make a program more reliable. When you use Set Zoom/Lights, InSpec will change the zoom and lights settings of the selected features to the current zoom and lights settings.

### Insert Here / Insert at End

The Insert features allow you to add features or copy features to rearrange the order that the features are measured. The insertion bar will be placed above the selected feature when you choose Insert Here, or at the end of the list when you select Insert at End.

### Inputs List

The Inputs list, located below the Features list, displays the individual components used to create the current feature. These entries tell how a feature was measured, whether vision tools or other features were used for data points. Inputs can be selected, edited, and deleted individually.



### Inputs Context Menu

Right clicking on an Input brings up the following menu:



This menu lets you do the following to the Input:


- Move Here – Drives the stage to where the Input was measured. This is available when vision tools are used as Inputs.
- Edit Prompt... – Displays a dialog box where you add and edit a prompt for the selected Input. The prompts usually are used to instruct the operator where to place the current tool. These are typically used at the beginning of a program or for manual points. If the Input is measured automatically, the prompt will only appear briefly on the screen.
- Pick Section – Allows editing of splines that have been used as inputs
- Delete – Allows deletion of the current Input.

## Chapter 3 The Program Interface

Information about your part program is displayed in the lower left corner of the screen. The features and inputs are listed on the left with the programming icons just to the right. This view will vary in appearance depending on monitor resolution.

### Features List

The Features list displays a list of the features in the program. Features are added to the list as you create them the first time. When a program is run, features will be measured in the order that the features appear in the list.



A feature is usually some entity on a part that can be measured. InSpec can measure several types of features including arcs, angles, circles, distances, ellipses, lines, o-rings, and points. Features are measured from data points, field of view tools, or constructed from other features. There are also text, prompt, command line, part separators, and temperature features.

A triangle on the right of the Features list indicates which is the “current feature.”

The “current selection” of features is highlighted.

Multiple features can be selected using the SHIFT and CTRL keys. Operations, such as deleting, setting tolerances, or copying, are applied to the current selection of features.

### Features Context Menu

Right clicking on a feature in the Features list will bring up the following menu:



This menu provides the following functions:

- Remeasure – Recapture data for the selected feature(s).
- Exports – Open an Exports dialog box to select export characteristics.
- Tolerances... – Open a Tolerance dialog to set tolerance values for the selected feature(s).
- Select All – Select all features in the program.
- Delete – Delete the selected feature(s).
- Rename ... – Change the name of the current feature.
- Translate ... – Copy or Move selected feature(s) in X, Y, and Z.
- Rotate... – Copy or Move selected feature(s) around the system origin.
- Mirror... – Copy or Move selected feature(s) across the X or Y-axis.
- Set System – Relate selected feature(s) to a different coordinate system.
- Store... – Name and Save a feature for use in other programs.
- Edit Solution... - Change some geometric constructions.
- Edit Text... - Change the content of a Text feature.
- Playback... - By enabling or disabling a feature, you can control whether it is measured the next time the program is run.
- Set/Clear Drive Point - Control the center location for capturing an image.
- Set Zoom/Lights – Changes the zoom and light settings for all selected features to the currently displayed zoom and lights settings.
- Insert Here – Place the insertion bar in front of the current feature.
- Insert at End – Place the insertion bar after the last feature.


### **Remeasure**

This command is useful to test a tool on an edge or verify that the position of a translated feature is correct without rerunning the entire program. If the feature precedes the first X-Y origin, the user will be prompted to manually remeasure. If the feature follows the first system, InSpec will move to and measure the feature automatically.

### **Exports**

InSpec allows you to select individual characteristics of each feature to be exported to a data file. You can select a single feature or a group of features when setting the characteristics to be exported.

The export dialog box is a “pin up” box that remains on the screen as you select other features and set exports. Use the “X” in the top right to close the dialog.



To open the Feature Exports dialog box, first select the desired features in either the schematic or the Features list. Right click on the features and select Exports from the context menu. The F4 hot key will also open up the Feature Exports dialog.

Check the boxes for the properties and options you want to use. When your selection includes multiple feature types, use the “Feature Type” drop down menu in the top left to select one feature type at a time.


- Export with Labels – This toggle allows the user to include labels with the exported data, such as “Circle 10: Diameter.”
- Export Nominals and Tolerances – This toggle will include tolerance values if available, for each of the selected properties.
- Property – These check boxes allow the user to specify which characteristics of the selected features are to be exported.
- Label – InSpec allows you to customize labels for exported data. If Export with Labels is checked, InSpec will include a label with the export data. If no label is entered, then a default label is created using the feature name and property. The label is in quotes to facilitate use in spreadsheet and SPC software, i.e. “Circle 1: Center X”.

### Tolerances

InSpec has the ability to tolerance linear, angular, form, and positional dimensions. Tolerances can be applied to a single feature or to multiple features.

For a single feature, the tolerance dialog box will display the available tolerances for the selected feature type, as well as nominal values and calculated deviations from tolerance.

For multiple features, the dialog will only display the available tolerances for the selected feature type. Nominal values will typically have question marks (???) indicating that the values for the the features are different. If a number appears in the nominal column, then all of the features have the same value, for example Z=0.



The tolerance dialog box is a “pin-up” box that remains on the screen as you select other features and set tolerances. Access the tolerance window through the Features Context Menu or by using the F3 hot key.

### Select All

This option can be used to pick all of the features in a program. You may want to use this so that you can immediately tolerance features or delete all features to start a new program.

### Delete

This is one of the most used features. When programming, you often find a better way to measure a feature or change you mind after selecting a feature type. When you use “delete,” InSpec assumes that you mean it and does not ask for confirmation.

### Rename

InSpec automatically names features with a number. The name can be changed to an alphanumeric phrase of up to 32 characters. The name is used in the program, summary, reports, and tags. No two features in the same program can have the same name. A dialog box will appear and allow you to enter your own name for the feature. The hot key for the rename dialog box is F2.



### Translate

The Translate function allows the user to apply a transformation to a feature or a group of features. First select the group of features and then select Translate from the Features Context Menu.




At the top of the Translate menu box, first select the reference system for the translation. The reference system will default to the parent system used by the feature directly above the 'Insert Here' line. The default reference system will not be appropriate for every case.

By checking the *Append copy number to feature names* box InSpec will add *\_#* to the end of each feature name (including the source feature). For example, when feature *Diameter* is translated two times along the X axis the result is *Diameter\_1*, *Diameter\_2*, and *Diameter\_3*:



And if all 3 are translated again along the Y axis the result is a grid where all of the feature names correspond to their relative position:



The *Copies inherit last system of preceding block* checkbox is used to translate a section of features such that each copy will be relative to the preceding copy (as opposed to each copy being relative to the system chosen in the dialog).

This can be particularly useful when making copies to track a curve or surface with unknown geometry such as the free form of a flexible piece of plastic. For example, if you translate the following group of three features relative to system PCS



it will create point 13, system 14, and point 15. The parent system for point 15 will always be

system 14, however the parent system for features 13 and 14 will either be PCS (if the *Copies inherit last system of preceding block* is not checked) or will be system 11 (if the *Copies inherit last system of preceding block* is checked).

### Linear


A linear translation command will move or copy the selected features.



After selecting the proper system, enter the values for the translation. You have the choice of making copies which will be separated by the given translation interval, or moving the selected features. The selected features will be copied or moved when you click on OK. Remember that these features have not been measured. It is often helpful to test the locations of copied features. You can select one of the features and use the Remeasure command to verify that the tool position is correct.

### Grid

The Grid tab allows for features to be translated along 2 different axes with a single step.




The option to Move first in X or Y will effect the numbering of the features created. The *Append copy number to feature names* option is useful to automatically create feature names that correspond to positions in the grid.

### Table

The Table tab provides the functionality of being able to create features or blocks of features in a pattern that is not defined by standard geometric shapes.





With this option, it is possible to copy and paste values from a spreadsheet into InSpec and create features at those locations.

### Rotate

The Rotate command in the Features Context Menu allows the user to rotate a feature or multiple features in a program around the current system origin. This simplifies the programming of gear teeth, bolt hole patterns and other symmetric arrangements of features. To transform multiple features, select the group of features and then select Rotate from the Features Context Menu. Enter the angle of rotation and whether to move the original features or create a number of copies.



Checking *Append copy number to feature names* will add # to the end of each feature name (including the source feature). For example, when *BoltHoleCircle* is rotated to create 3 copies, the result will be *BoltHoleCircle\_1*, *BoltHoleCircle\_2*, *BoltHoleCircle\_3*, and *BoltHoleCircle\_4*.

### Mirror

The Mirror command in the Features Context Menu allows the user to flip a feature or multiple features in a program across the X or Y-axis. This simplifies the programming of symmetric features. In the Mirror dialog box, select the axis to mirror across and whether to move the original features or create a copy.



The *Append copy number to feature names* check box will add *\_#* to the end of each feature (including the source feature). For example, the result of making a mirrored copy of *Line4* would change the original feature to *Line4\_1* and create *Line4\_2*.

### Set System

Set System gives the user flexibility for taking measurements relative to different coordinate systems. Users will find that although they wrote a program to measure a feature relative to one coordinate system, they may want to know the location relative to a different system or to second system.

### Store Feature

InSpec software allows features to be stored in memory, so you can use them in other programs.

Storing a Feature is simple. First, Create a feature. Then choose *Store* from the Features Context Menu (right click on the feature name). The following dialog will appear:




Check the box next to *Store As* and enter a unique name. By checking the *Store Permanently* box you will save the feature permanently. If you do not check the box, the feature will be saved only for the current session of InSpec and will be deleted when InSpec is closed.

Fixtures are often used to position parts on the stage. By storing and using the location of a fixture, part programs can run completely automated without operator input. All the operator has to do is load the part and click on the Run icon.

First make a short program that creates a system origin and skew on the fixture. Store the system. Then begin the part program with a system that "Recalls" the stored feature. When you run the part program, InSpec will know where the part is supposed to be and can begin measuring without any user input.

### Edit Solution

There are a number of constructions that have multiple solutions. For instance a line may intersect with a circle in two locations. When you program a part a dialog box will pop up and allow you to select the correct solution. However if the wrong solution was selected, the Edit Solution option can be used to view and select the correct construction. The bold crosshairs shows the selected construction point.



### Edit Text

This option will allow you to edit existing text in a Text and Prompt type features. The dialog will give you the options to accept, reset, and cancel any changes.

This feature is convenient for exporting text to a data file, especially for cases where the text does not change very often. For instance, if you measured twenty samples per lot, the text message may say "LOT #7909." This could be exported with the data. For the next lot of twenty samples, you could Edit Text to change the number. This would be more convenient than using a Prompt feature that requires user input for each run.

### Playback

The playback setting can either be set to enabled or disabled. By default it is set as enabled, which means that when the program is run again, the feature will be measured. When the playback is set to disabled, the feature will become light gray in the schematic, and will not be measured next time the program is run.

A disabled feature will not appear in the Log View. If another feature is dependent on a playback-disabled feature, it will not measure either. You should not use playback-disabled features to define systems, or as constructions.

A disabled feature can be useful if the programmer would like to reference an outline of the part in the schematic, but does not actually want to measure the outline each time the program is run.

### Set / Clear Drive Point

Drive Points can be used to reduce measurement time or for special lighting.

Normally InSpec drives to the center of a tool and "grabs" an image.

Drive points allow the user to define the X-Y-Z location of the "grab" for a feature.

If a three by three array of holes fit in the field of view, you could position the stage on the center hole, select the nine diameters, and then set the drive point. During the run of the program, InSpec will take a single snapshot and use it to take measurements of all nine holes.

Likewise if the four sides of a small rectangle fit in the field of view, drive to the center, measure the four sides with F-Scan Line tools, and set the drive point for the rectangle. Then move on to the next feature.

If lighting is better with a feature off-center, use the drive point to lock the X-Y-Z position of the image grab.

### Set Zoom/Lights


The lighting and zoom settings are important for a program to run consistently from one part to the next. It may be helpful to raise the lighting or to decrease the zoom setting to make a program more reliable. When you use Set Zoom/Lights, InSpec will change the zoom and lights settings of the selected features to the current zoom and lights settings.

### Insert Here / Insert at End

The Insert features allow you to add features or copy features to rearrange the order that the features are measured. The insertion bar will be placed above the selected feature when you choose Insert Here, or at the end of the list when you select Insert at End.

### Inputs List

The Inputs list, located below the Features list, displays the individual components used to create the current feature. These entries tell how a feature was measured, whether vision tools or other features were used for data points. Inputs can be selected, edited, and deleted individually.



### Inputs Context Menu

Right clicking on an Input brings up the following menu:



This menu lets you do the following to the Input:

- Move Here – Drives the stage to where the Input was measured. This is available when vision tools are used as Inputs.
- Edit Prompt... – Displays a dialog box where you add and edit a prompt for the selected Input. The prompts usually are used to instruct the operator where to place the current tool. These are typically used at the beginning of a program or for manual points. If the Input is measured automatically, the prompt will only appear briefly on the screen.
- Pick Section – Allows editing of splines that have been used as inputs
- Delete – Allows deletion of the current Input.

## Chapter 7 Other Icons

### Schematic Zoom

Customers use Micro-Vu systems to measure a variety of parts. Some larger parts have small features. InSpec provides zoom capabilities in the schematic so that you can view the relative position of these features.

Use the Fit and Zoom Icons directly below the Schematic window to zoom in on smaller features and zoom out to see the entire Schematic.



The Zoom-In icon toggles between the “Zoom” state and the “Pick” state. When the button is pressed, the mouse cursor will show a magnifying glass when the mouse is in the Schematic window. To zoom in on features, click-and-drag a window around the area you would like to enlarge.



The Zoom-Out icon incrementally decreases the zoom so that you can make slight increases to the field of view.



The Zoom-to-Fit icon changes the Schematic zoom to display all of the features in the program and the location of the current stage position. Note that if the camera location is not near the part and the part is relatively small, then the part features will appear small on the screen.

### Tags



The Tags icon allows the user to mark selected features on the Schematic. This makes it easier for the user to locate specific features. The user may select a group of features from the Features list and change the tag status for all of the selected features at one time. A feature's Tag displays the number or name of the feature. When a feature is renamed the feature's name is displayed in place of its number.

### Playback Icons

The Playback icons allow the user to start from the beginning, stop, and continue the playback of a part program.



#### Run

The Run icon starts the current measurement program from the top of the Features list. Manual points and features measured to create the first system will require operator input.



#### Continue

The Continue icon restarts the measurement after the process has been paused or stopped. Continue starts the program from the current feature and progresses down the program list. This allows the user to stop the program, skip features, and restart the measurement process if needed.



#### Stop

The Stop icon will stop the measurement of a program. While stopped, measured features can be checked and remeasured if needed. Use Continue to restart the measurement process.



#### Reduce Speed

The Reduce Speed icon is only available when the touch probe is attached. It acts as a toggle between two speeds. When you click on it, the button will stay down until you click on it again. This function is helpful when testing touch probe programs. It gives the operator more time to stop the program in cases of a collision.

## Chapter 8 Beginning to Measure

Micro-Vu's InSpec software provides an easy-to-use, point-and-click style to create measurement programs. InSpec records the lighting, zoom, and stage position settings for each tool as you "teach" the first part.

Not only are programs easy to create, they are also easy to edit. Because of the Feature-Input structure of the program created in InSpec, the user is allowed to go back and change individual steps of the program.

When you open InSpec, the schematic window, features list, and inputs list will be empty. As you teach InSpec the features on a part, the features will appear in the schematic and be listed in the features list. The individual tools used to create each feature will appear in the inputs list. You can save and open files from the File menu as you do in other Windows based programs.

### Measuring the Sample Part

The following section shows step-by-step, icon-by-icon, how to measure a few features on the sample part. Follow along step-by-step. Some of the steps are explained as they occur. Others are better explained later in the manual. You should be familiar with the basic Windows operations and the InSpec user interface before beginning.

#### Preparation


- Turn on the computer and machine
- Double click the InSpec icon to start InSpec.
- Use the drop-down menu in the camera window to set the zoom to the lowest magnification (i.e. approximately 15x, or similar depending on machine).

Using low magnification makes moving the stage easier for the beginner and allows you to use "Field of View" tools on more features.

*If the zoom drop down menu has numbers preceded by the pound (#) character, then a screen calibration needs to be performed before continuing.*


Set the profile lighting to approximately 20-30% and turn the other lighting off.

- Orient the sample part on the stage as shown below. It is good practice to use clay or clips to hold the part in place.



#### Creating a System


To get a program to run on its own, a part coordinate system must be established. Create a coordinate system on the lower left-hand corner of the part. The corner can be located by intersecting two lines. Begin the program by creating a line near the lower left-hand corner of the part.

- Click on Line  from the feature icons and select the Feature




Scan Line from the tool icons.

- Left click in two places on the horizontal edge. **Line 1** will be displayed in the Features list. InSpec will create a search zone displayed with the dashed line. The image will be processed and a magenta line will show the operator the measured line segment. The width of the search zone can be adjusted by click and dragging the dashed line. The length and position can be adjusted by click and dragging the control points, the green boxes.





To remind the next operator where this line was measured, a Tool Prompt can be displayed.

- With **Line 1** highlighted in the Features list, right click on the text in the Inputs list. This will display the Inputs Context Menu.
- Click on Edit Prompt and the Tool Prompt dialog will appear allowing the desired text to be entered.
- Type, "Measure a horizontal line near the lower left corner of part." The text will be displayed when you run the program.
- Move the stage to view the vertical edge of the part. Notice that the field of View Line tool is still selected.
- Left click twice on the vertical edge. **Line 2** will be displayed in the *Features* list.





- Add another Prompt as a reminder.
- Select **Line 2** in the *Features* list, right click on the text displayed in the *Inputs* list, select Edit Prompt, and enter the text to be displayed during playback. Type, "Create a vertical line near lower


left corner of part.”

- Now create a point at the intersection of the two lines. Click on Point  from the Feature icons and then on Intersect  from the Construction icons. Now point and click on **Line 1** and then **Line 2** in the *Features* list with the mouse.

You can select Line 1 and Line 2 from the *Features* list or from the schematic. Notice that the shape of the pointer changes to a hand when the object beneath is a valid input. When the pointer is over a feature in the schematic window, the feature will change from green to pink. A point will appear on the schematic as a small crosshairs. **Point 3**.

A coordinate system is needed to establish a “zero” point and to set the alignment of the counting direction to that of the part.



Click on System  feature icon and **System 4** will appear in the *Features* list. Click on Skew  from the Construction icons. Skew to **Line 2** by clicking on **Line 2** in the *Features* list or in the Schematic window. The Skew construction will appear in the *Inputs* list.

- With **System 4** still highlighted, click on Origin  from the construction icons to create and X-Y-Z origin. Select **Point 3** by clicking on **Point 3** with the hand. The Origin construction will appear in the *Inputs* list.

A coordinate system will be displayed on the Schematic with an arrow indicating the positive X direction. The counting direction is aligned to the part and the intersection point is now (0,0,0).


Now add more features to the program. InSpec records the offsets relative to the origin. This allows the program to run automatically the next time, after the origin has been established.

Move the stage so that one of the circles is completely in the Camera Window.


- Click on Circle  from the Feature icons and select the Field of View Circle  from the Tool icons.



- Click the three points on the circumference of the circle to place the Field of View Circle tool. In the Camera Window, click and drag the dashed lines of the tool to change the size of the search zone. **Circle 5** will appear in the *Features* list.


The search zone will change from green to yellow if the zone exceeds the bounds of the view. The size of the tool must be reduced until it fits in the view and can compute the edge (40x or lower magnification is needed). The small green boxes are Control Points. Click and drag the control points with the mouse to adjust the position of the tool.



If the circle does not fit in the camera window, select the Best Edge  from the tool icons and place three points on the circle.








- Move the stage so that the lower right arc is in the field of view.
- Click on the Arc  from the Feature icons and the F-Scan Arc  from the Tool icons.
- Click three points on the arc. **Arc 6** will appear in the *Features* list.



- Move the stage so that another circle is in the field of view.
- Click on Circle  from the Feature icons and then select the Best Edge  from the Tool icons. Now select three points on the circle. As the points are entered, **Best Edge** tools will appear in the *Inputs* list.




- Move the stage so that the upper left-hand portion of the part is in the field of view.

- Click on Line  from the Feature Icons and then the First Edge  from the **Tool** icons. Click on two points along the line.

After the points are entered, a **First Edge** tool will appear in the *Inputs* list. Notice that this is a point tool. You have entered one of two points needed to construct a line. The arrow on the tool indicates the directions of the search. A light blue line will trace the chosen edge, and a magenta cross at the center of the line represents the single data point reported by the tool.

- Move the stage to the other end of the line and click twice more along the line to place a second First Edge point.

The line is now complete and will be drawn in the Schematic. Notice that you can click and drag the control points (green squares) of the tool. You can also click and drag the dashed edge of the search zone to resize and change the direction of the tool.




### Running the Program

- To run the program click on the Run  icon.


InSpec will highlight the first feature in the Feature list and the prompt will appear. Notice that the F-Scan Line tool has already been selected for you.

Move the stage so that the lower left-hand corner of the part is in the field of view and create the line tool on the horizontal edge, and enter the horizontal line.



- Click on Continue  and InSpec will advance to the next feature.
- Move the stage to view the vertical edge. Then click twice to create a line tool on the vertical edge.



- Click on Continue  after you have entered the vertical line and the program will continue. The features following the two lines will run automatically because InSpec now has enough information to construct the point and then create the system origin. After it has an origin, InSpec knows where to look for the remaining features. The software automatically moves the stage and places the tools at the programmed locations, collecting data for the remaining features.

Now add the other circles, the lines on the other edges, and the other arc to the end of the program.

- Move the sample part to a different location on the machine and rerun the program. It should run the same way, prompting you for the first two lines and then automatically measuring the remaining features.

### **Saving the Program**

- Select Save or Save As from the File menu.
- Give the file a name such as "Tutorial" at the File Name prompt and then click on Save.

Notice that the default directory for saving and opening a file is C:/InSpec Documents.

- Select New from the File menu to start another program.

In an effort to simplify the user interface, InSpec only allows one program to be active at a time. Tutorial will no longer be open.

### **Loading and Running a Program**

- Click on File to display the File Menu.
- Select Open from the list of options.
- Browse through the file listing directories to find Tutorial. Click on Tutorial and then on Open, or double click on the file name.  
The Features list and graphic will load.
- Click on the Run Icon to run the program.

## Chapter 9 How to Measure Your Parts

InSpec for Windows provides a powerful metrology software package while keeping the user interface simple. With the previous example you can see that it is easy to measure the sample part, but now how do you measure other parts.

Considering the diversity of our customers and their parts, it is a challenge to write a “How To” manual that will explain how to measure every part. This section provides some “typical” measurements examples and programming tips. By applying the concepts in this chapter, you will have a good foundation to build a program for measuring “any” part. Keep these steps in mind when creating a part program.

- Plan your measurements
- Set light levels
- Stay in focus
- Create a coordinate system
- Measure features

### Planning a Program

The first step to writing a program is to identify the features that you need to and can measure with the Micro-Vu system. Proper planning can save you time programming and running parts.

Look at the part and identify the order in which you need to take the measurements. For example, you need to measure datum features before you can measure other features that relate to the datum features. Also consider the order of features to minimize long moves of more than a few inches. For example, you can measure the perimeter features of the sample part and then do a distance between the features instead of measuring the left side followed by the right and then the top followed by the bottom of the part.

For more advanced programs, you will want to look for easy starting points such as features that are easy to locate or a way to fixture the part. Using an easy-to-locate feature or a fixture, you can write a program that requires a single input or no input to begin automatically measuring a part.

An InSpec program will not start automatically measuring the part until an initial coordinate system is set. This is typically created from the datum features on a part print. The initial coordinate system information tells InSpec where the part is located on the machine and how the part is aligned. After establishing the initial coordinate system, InSpec knows where to begin looking for the edges of the following features. Later in the program, additional coordinate systems can be added.

### Plan your Measurements

Planning your measurements will save you programming time and shorten the overall run time of the program. Ask yourself the following questions.

How is the part going to be held in place?... With clay? Against an 'L' bracket? In a fixture of multiple parts?

How are you going to build the initial system? What features are needed to start the program? Can you use the RefSys?

What measurement order will minimize move time between features? This is a relatively minor issue except on large parts.

### Selecting Light Levels

Lighting can have a large impact on image quality and edge definition. When selecting lighting, it is

important to make edges appear as crisp as possible. Sharp edges will produce more repeatable and more likely to work on the next part that may not have the same surface finish.

The best way for beginners to learn proper lighting is to look at a variety of parts and try different lighting. The best words of advice are “Not too little, not too much” and “experiment.”


**Coaxial Light** or “Through the Lens Light.” In a video system, coaxial light refers to an illumination source that is parallel to the optical axis. This is usually achieved with a right angle beam-splitter between the lens and the camera.

**Profile Light** Illumination that originates from behind (under) a part directed upwards toward the lens/camera system. This lighting technique is very good for illuminating flat parts.

**Surface Light** or “Ring Light.” In this application, surface light refers to illumination from above the part. The light is reflected off the surface of the piece. Usually, surface lighting is some form of ring light around the lens.


## Creating a Coordinate System

The purpose of the initial system is to give your program a place to start. It tells the program the location and the orientation of the part on the machine. Your initial system is the cornerstone of your program. With a reliable initial system, your program will require few if any changes.




Systems are very important. If the location of the origin is incorrect, the error will be present on any locations of features. If the skew is inaccurate, an error will be present and increase the further a feature is located from the origin. A bulletproof system will have a precise ORIGIN in X, Y, and Z and a precise SKEW.

Before creating the initial system, take a good look at your parts and prints. You need to find a feature with LOCATION and a feature with ORIENTATION. These features are often the datum features on the prints, but other features may be used.



### LOCATION

The initial system needs a starting point on the part. The LOCATION feature(s) tell the program where the part is located on the machine. This X-Y position needs to be repeatable from one part to the next but does not have to be the same as the datum as described on the part print. Good examples include a point at the intersection of two lines and the center of a circle. Bad examples are the center of a line or a point on a curve.



### ORIENTATION

The initial system needs to know how the part is aligned and in what direction the X- and Y-axis are aligned. The ORIENTATION feature(s) tell InSpec how the part is skewed on the stage. Again, this alignment needs to be repeatable from one part to the next but does not have to be the same as the datum as described on the part print. Good examples include a line, which can be an edge on the part, or a line between two holes. Any feature that has “direction” can be used.

## Skew

### Length Matters


When picking the features that will be used for the skew of a system, keep in mind that length does matter. A longer line will have less angular error than a short line. For instance, a feature scan line at low magnification will use a 0.100" segment of an edge. A deviation of less than 0.0002" in the Y direction from end to end translates to an angular error of 0.1°. That doesn't seem like much. But if you now measure a hole 4" from the origin along the X-axis, you will have a 0.007" deviation in the Y position due to the sine error.

The deviation of less than 0.0002" over a line of 4" would produce a much better skew reference with an angular error of less than 0.003°.

The skew of the coordinate system can have a large affect on measurements, especially of larger parts. Skew to long lines created with multiple points to reduce errors.

### Edit Skew Offset

Some parts have a datum which is offset from measured features. For these parts, there is the Edit Skew Offset functionality which allows you to manually enter the distance.



This option is only available for system features whose skew is defined by 2 points. It is accessed by right clicking on the system feature and choosing Edit Skew Offset. The value inputted by the user is the perpendicular offset distance between the second skew point and the print datum.

### Stay in Focus – Z-Origin

The most overlooked part of most programs is the Z-origin. If you do not include a focus point and a Z-origin in the beginning of your programs, images may be out of focus when you measure parts. Focus and Z-height are synonymous. When you focus, you are locating the Z-height of the part.

Focus problems are more visible when using high magnification. Because of the smaller depth of field at high magnification, the image appears blurry when slightly out of focus. At low magnification the depth of field is larger, and small changes in focus/Z-height appear to have little affect on the image. However, being out of focus at any magnification reduces measurement accuracy and produce poor repeatability.

**A focus point and Z-origin should be included before datum features are established.** A focus point may be the first feature in the program or may be several features later. Later in the manual we discuss building a bulletproof system and give an example that adds a focus point to the system. Using a focus point and setting the Z-origin before selecting datum features provides sharper images, hence better accuracy and repeatability, for the tools used to create datum features.

**A good program will include a focus point and Z-origin each time there is an increase of magnification.** Focus is less repeatable at low magnification than at high magnification. If I focus on my part at low magnification and zero the origin, the part will appear to be in focus. When I increase magnification, the image may look blurry. It is important to refocus at the high magnification and zero the Z-origin. This will ensure that tools used at this magnification will be in focus when the program runs even if the focus at low magnification is less repeatable.

**A good program will include a focus point and Z-origin for each change of height.** Many parts will have features at different heights. From one part to the next, the heights will be different, varying by the acceptable tolerance of the part. A part may have some features at one level and then others on another surface an inch higher. On the first part the features may be 0.995", on the next they may be at 1.005". The edges would appear out of focus. Take a focus point and set the Z-origin. Then measured height will be used as the reference instead of the nominal height of

1.000". The images will be in focus and accuracy and repeatability will be better.

## Creating a Feature

The icons between the instruction list and the camera window are divided into three main sections. On the left are the features. Feature icons are the types of entries that can appear in the instruction list. To create a feature, select the icon for the feature you want.

Select from point, line, circle, arc, distance, angle, ellipse, rectangle, slot, gap, spline, o-ring, and system.

Selecting a feature icon will place a feature in the instruction list. InSpec uses a "closed" feature architecture that requires the feature to be completed or deleted before allowing the user to work on another feature. You must provide enough points to construct the current line, circle, or rectangle before you can begin the next arc, point, or distance.

As with any job, you will get better results if you use the correct tool. Using a hammer to pound nails usually works better than using a shovel. Refer to the tool descriptions in previous chapters for tips on choosing the correct tools.

## Using Magnification

The programmable zoom lens gives the Micro-Vu system the flexibility to easily locate parts as well as to accurately measure very small features. For the best focus repeatability, a medium to high power (and for the zoom lens, a 2X multiplier) works well. If heights or very small features are not necessary, most users prefer to use lower magnification so that more of the part can be seen. Furthermore, at lower magnification, the depth of field is greater. This is can be advantageous for edges that exhibit variation in the Z direction. Although the surface varies in Z, it will appear to be in focus.


## Chapter 10 Application Tips

InSpec for Windows is an incredibly flexible metrology software package. It is used by customers measuring sheet metal panels with tolerances of  $\pm 0.020$ " as well as customers measuring fiber optic connectors with tolerances of  $\pm 0.000020$ ". Parts vary in size, shape, weight, material, and texture. The objective of the InSpec software is to provide an easy-to-use metrology solution that meets most customers' needs.

Considering the diversity of our customers and their parts, it is a challenge to write a "How To" manual that will explain how to measure every part. This section provides some "typical" measurements examples and programming tips. By applying the concepts in this chapter, you will have a good foundation to build a program for measuring "any" part.

### Making an Initial System

The following steps outline how to create a simple initial system at the bottom left corner of the sample part. These steps provide a well defined location and orientation of the part. This example is repeated with icons and pictures in the next section, Measuring the Sample Part.



- Place the sample part on the machine.
- Activate the profile lighting and click on *Auto Lights*.
- Set the magnification to the lowest setting.
- Position the stage so that you can see the bottom left corner of the part on the screen. Make sure that the part is in focus.
- Select the Line feature icon.
- Select the Line tool icon.
- Click in two places on the bottom edge of the part to create a horizontal line. This will create feature Line 1.
- Click in two places on the left edge of the part to create a vertical line, feature Line 2.
- Select the Point feature icon.
- Select the Intersect icon.
- Click on Line 1 and Line 2 to create a point at the intersection of the two lines. Now you have a Point that has a well defined LOCATION and a line that has DIRECTION.
- Select the Skew icon.
- Click on the horizontal line. The system will be aligned to the horizontal line.
- Select the System icon.



- Select the Origin icon.
- Click on the Point. The system will be “zeroed” to the point.

## More Simple Programs

After you are comfortable with the steps above, read through and practice the following programming tips.

### Same Sample Part, New Origin

Because InSpec is so flexible, there are often more ways than one to locate a feature or make a measurement. Using the Sample Part again, use the following steps to make another system with the origin at the center of the bottom left circle and skewed to the bottom edge.

- Activate the profile lighting and click on *Auto Lights*.
  - Set the magnification to the lowest setting.
  - Position the stage so that you can see the bottom left corner of the part on the screen.
  - Select the Line feature icon.
  - Select the Line tool icon.
  - Click on the bottom edge of the part in two places to create a horizontal line.
  - Select the Circle feature icon.
  - Select the Profile Circle icon.
  - Click at the center of the circle and then click and drag the dash circle to encompass the hole.
  - Select the Skew icon.
  - Click on the horizontal line.
- The system will be aligned to the horizontal line.

- Select the System icon.
  - Select the Origin icon.
  - Click on the Point.
- The system will be “zeroed” to the point.

- Add a few additional features and run the program.

### Same System, One Feature

Using the same hole and line as above, you can create the same system with a single feature. The only difference between this example and the previous example is the picture in the schematic. The only feature that is actually defined in the following example is the system. Therefore, only the system will appear in the schematic, not the original line and circle.

- Activate the profile lighting and click on *Auto Lights*.
- Set the magnification to the lowest setting.
- Position the stage so that you can see the bottom left corner of the part on the screen.
- Select the System icon.
- Select the Skew icon.
- Select the Line tool icon.
- Click on the bottom edge of the part in two places to create a horizontal line.
- Select the Origin icon.
- Select the Profile Circle icon.
- Click at the center of the circle and then click and drag the dash circle to encompass the hole.

- Add a few additional features and run the program.

Now you have created the same system as above but with a single feature. Sometimes this is easier for the operator to understand. Sometimes it is more difficult because the circle and line used to establish the system are not displayed. Notice that only the system is displayed on the schematic view of the part. This can be confusing unless user prompts are added to describe which features were used.

## Building A Bulletproof System

As mentioned earlier, coordinate systems are very important to ensure the accuracy of your measurements. A bulletproof system will have a precise ORIGIN in X, Y, and Z and a precise SKEW.

To build a bulletproof system, you can start with a rough initial system. Once you have an initial system, program the features that will be used to make your final system. Start by zeroing the Z-axis on a focus point to ensure that the following features will be in focus. Use multiple points to define the datum features. Remember to use the entire length of a line to minimize skew errors.

InSpec does not limit the number of systems in a program. You can use a simple initial system to get the program started. Then measure some additional features to define the system better. Then construct a third or fourth system to represent the datum features. Remember that this is an automated system. Have the machine and software do the work of finding features and building a bulletproof system. This also reduces any error contributed by the operator.

### Start with a Point

The next example shows that with some assumptions, you can start a program with a single manual point.

Place the sample part on the machine aligned to the X and Y axes.

The following steps will create a system at the bottom left corner of the sample part.

- Activate the profile lighting and click on *Auto Lights*.
- Set the magnification to the lowest setting.
- Position the stage so that you can see the bottom left corner of the part on the screen.
- Select the System icon.
- Select the Origin icon.
- Click on the Manual Point tool.
- Click on the corner of the sample part.

The system will be “zeroed” to the point. This is just a starting point. Even if you are off by five or ten pixels, the program will still run.

- Select the Line feature icon.
- Select the Line tool icon.
- Place the line tool on the bottom edge starting about half an inch (onscreen) from the corner and about two inches long. Make the search zone at least two inches wide.
- Select the Line feature icon.
- Select the Line tool icon.
- Place the line tool on the left edge starting about half an inch (onscreen) from the corner and about two inches long. Make the search zone at least two inches wide.

By programming the search zones for these two lines to be wide and close to the origin, the program is likely to find the edges even if the part is not aligned with the axes of the machine. We assume for this program that the operator can place the part on the stage within +/- 10° of the X-Y alignment of the stage. As long as the part is more-or-less straight on the stage, the program will

run.

- Select the Point feature icon.
- Select the Intersect icon.
- Click the Line 2 and Line 3 to create a point at the intersection of the two lines.  
This point will be a better origin than the manual point.
- Select the System icon.
- Select the Origin icon.
- Click on Point 4.
- Select the Skew icon.
- Click on the horizontal line. You will have a new system. It is better but not great.
- Select the Point feature icon.
- Select the Focus Point tool icon.
- Click on the corner of the part.
- Select the System icon.
- Select the Z-Origin icon.
- Click on Point 6. This establishes an initial Z-plane for the part.
- Select the Line feature icon.
- Select the Best Edge tool icon.
- Select More Inputs mode.
- Place three edge tools, one near the corner, one near the center, and one near the opposite end of the bottom edge.
- Select the Line feature icon.
- Place three edge tools, one near the corner, one near the center, and one near the top of the left edge.
- Select the Point feature icon.
- Select the Intersect icon.
- Click the Line 8 and Line 9 to create a point at the intersection of the two lines.  
This point will be a better origin than the previous point.
- Select the System icon.
- Select the Origin icon.
- Click on Point 10.
- Select the Skew icon.
- Click on the horizontal line.

Now you have a new system that has a well defined X-Y-Z Origin and a well defined skew. This system is probably much more than needed. Carefully consider your coordinate system when you are measuring parts with tight tolerances.

Z-axis position and focus are important for accurate measurements.

If measurements are taken in one plane, then you need one Point feature created near the beginning of the program that uses a Focus Point tool. Then a system should be created and the Z-axis origin should be set to the Point. The Z value should be very close to zero for the features that follow.

For the best program, this should be done every time there is a change in Z position. Create a point feature with a focus point tool and then set the Z origin to the point.

## Finding Small Features

The area that the vision tools search for the desired edge is always based upon the current coordinate system. With this in mind, if a feature's size is comparable to the tolerance of the feature's position, it may become difficult to reliably find the feature in an automated program. One suggestion is to set a new coordinate system upon some larger feature that is close by the small feature. Many times, the incremental distance between the two features is much more tightly constrained than the distance from a far away origin. In this way, the Measuring Center™ can reliably find the larger feature and use it for zeroing in on the smaller one.

For example, if a large rectangular part has an origin in the lower left corner and located in the upper right corner is a .050" hole with a positional tolerance of .050". Finding edges based upon the initial origin may be difficult since the hole can move around a distance of its entire diameter. Now suppose that the hole is much more tightly dimensioned to the upper right corner. If so, find the vertex of the upper right corner and set a new origin at that spot. Now we should be able to reliably find the small circle since we have "bootstrapped" off a larger (and easier to find) feature.

## Parts with Concentric Features

The geometry of some parts allows the user to use some tricks. For instance, many customers measure round parts with concentric features. Because of the geometry of the part and some assumptions that the parts will be fairly close to the nominal values, an initial system can be created with only an Origin. The system skew will not be important because of the symmetry of the part.

For these parts you can use a manual point at the center of the part or a tangent point line of a circle located with one of the cross hair lines. These points are easy for the operator to identify and can give the system enough information to locate the other features on the part.

## Diameters on Tapered Parts

Measuring the diameter at a nominal distance from the end:

Example: measure the diameter 4" from the end of the part. The print calls for a 1.00" diameter +/-0.05". Put the system at the end of the part, and skew to the centerline of the taper. Create points at (4,1,0) and (4,-1,0) using the point offset. Create a line between the two points. Create intersection points with the line and the top and bottom edges of the taper. Take the distance between the two intersection points. Set the tolerance of the Y distance to be 1.00 +/-0.05".

Measuring the location where a ring gage would fit on a taper:


Example: measure where the diameter is 1". The print calls for a location of 4.00 +/- 0.01". Put the system at the end of the taper, skew to the centerline of the taper. Create points at (3.5,0.5,0) and (4.5,0.5,0) using the point offset. Create a line between the two points. Intersect the line with line on the top edge of the taper. The X location of the point is the location of the 1" diameter. Set the tolerance of the X position to be 4.00 +/-0.01".

## Optimizing Programs for Speed

There are many ways to optimize inspection programs for speed. A major way is by the use of drive points. By using drive points, all of the vision tools which fit within a snapshot can be measured at the same time. The effect of drive points can be enhanced by using low magnification, and by using vision tools with small search zones. Drive points can be applied automatically or manually.

### Auto Generate Drive Points

This function will look at all of the vision tools that are used in a program and group them based on proximity. When the program is run, multiple features will be measured at the same time – eliminating the time spent driving to the center of each vision tool. To use this function go to the Tools menu and choose 'Auto Generate Drive Points'.



A dialog box lets you pick whether you want to apply the drive points to all features or just selected features. Another dialog shows the reduced number of snapshots and the time reduction.

### Manually Setting Drive Points

The 'Auto Generate Drive Points' function does not group together features which have different parent systems. For features which can be measured in one field of view, but have different parent systems, use a manual drive point. Do this by selecting all of the features that can be measured with a single snapshot, right click and choose 'Set Drive Point'.

### Reduce Setting Changes

Each time the machine changes from high magnification to low magnification it takes approximately 5 seconds. By thinking ahead and grouping features which are measured at the same magnification, you can avoid time lost by changing zoom frequently.

Likewise, it takes a few seconds when you change between using vision and touch probe. Write your program so that all of the touch probe features are taken sequentially, without repeatedly changing back to vision.

### Fixturing

Using a fixture for your part will help inspectors start programs more quickly. To best take advantage of a fixture, use a stored system which remembers the measurements of the fixture. More information on this is located in the Stored Features section of Chapter 14.

### Notes

For complicated setup procedures, you can write notes detailing how the inspector should begin the program. The notes can be incorporated in InSpec via a text feature or a prompt. A prompt feature will stop the program until the operator has acknowledged it (by hitting enter or clicking 'OK'). A text feature will not stop the program, but will not be visible unless the operator clicks on the feature.

## Chapter 11 Setting Feature Tolerances

With InSpec you can set bilateral, form, true position, and profile tolerances, including tolerances using reference features. Once values have been entered, InSpec will display a green check mark or a red "X" in the feature summary window to indicate that the feature is in tolerance or not.

Tolerances can be applied to a single feature or to a block of features.

InSpec allows feature tolerances to be added to individual features in your programs. In a single dialog box, InSpec will display the pertinent information of the selected feature with regards to the tolerances.

Property	Actual	Nominal	Upper	Lower	Dev/Nom
Center X	312.80575	312.75000	0.07500	-0.07500	0.05575
Center Y	520.75416	520.75000	0.07500	-0.07500	0.00416
Center I	607.48031	607.44804			0.03227
Center B	59.0028	59.0043			-0.0016
Center Z	74.98523	74.98523			0.00000
Radius	1.41206	1.42500			-0.01294
Diameter	2.82411	2.85000	0.02500	-0.02500	-0.02589
Circumference	8.87221	8.95354			-0.08133
Area	6.26402	6.37946			-0.11537

If a block of features is selected, the dialog will display the pertinent information for the selected feature type indicated in the top left of the box.

### Types of Tolerances

#### Bilaterals

Bilateral tolerances include basic size and location tolerances.

#### Position RFS

Nominal values define the location of a feature. The true position RFS sets a diametric tolerance zone for the position of the feature. The tolerance is independent of size of the feature.

#### Position MMC

Nominal values define the location of a feature. The true position MMC sets a diametric tolerance zone that increases as the feature deviates from its maximum material condition. The tolerance is dependent on the size of the feature.

#### Position LMC

Nominal values define the location of a feature. The true position LMC sets a diametric tolerance zone that increases as the feature deviates from its least material condition. The tolerance is dependent on the size of the feature.

#### Straightness

Straightness is a form tolerance with the condition that the element of a surface or an axis is a straight line. The tolerance is determined by placing a zone about the line where all the points must lie.

### **Circularity**

Circularity is a form tolerance with the condition that all the points lie equidistant from a center (used to determine how round a circle is). The tolerance is determined by placing two concentric circles about the center where all the points must lie.

### **Flatness**

Flatness is a form tolerance where the surface has all points in one plane. The tolerance is determined by placing two parallel planes about the desired plane where all points must lie.

### **Perpendicularity**

Perpendicularity is an orientation tolerance with the condition that a surface, plane, or axis is at a right angle to another. The tolerance is determined by two parallel lines constructed perpendicular to a datum or an axis. The data points must lie between the constructed lines. The gap distance between the constructed lines is the perpendicularity value.

### **Parallelism**

Parallelism is an orientation tolerance with the condition that a surface, plane, or axis is equidistant at all point to another. The tolerance is determined by two parallel lines constructed parallel to a datum or an axis. The data points must lie between the constructed lines. The gap distance between the constructed lines is the parallelism value.

### **Angularity**

Angularity is an orientation tolerance with the condition that a surface, center plane, or an axis is at a specified angle from a datum plane or axis. The tolerance is determined by two parallel lines constructed at the specified angle relative to a datum or an axis. The data points must lie between the constructed lines. The gap distance between the constructed lines is the angularity value.

### **Concentricity**

Concentricity is where all the data points are congruent about an axis or another feature. The tolerance is determined by placing a circle about the axis or the center of a feature where all of the data points of the second feature must lie. In other words, it tells how close are the centers of two features.

### **Profile of a Line**

Profile of a line establishes a two-dimensional tolerance zone around a nominal feature. The value of this bilateral tolerance is determined by doubling the distance from the nominal feature to the maximum data point. Nominal values for the feature must be entered. The current system acts as the datum references. If there are no datum references, create the feature, set a system origin on the feature, create duplicate feature, and tolerance the duplicate feature.

### **Profile of a Surface**

Profile of a Surface establishes a three-dimensional tolerance zone around a nominal feature. The value of this bilateral tolerance is determined by doubling the distance from the nominal feature to the maximum data point. Nominal values must be entered for the feature. The current system acts as the datum references.



### Circular Run-out

Circular Run-out is a two-dimensional tolerance zone defined by the minimum and maximum distances of a feature surface to a reference point. This tolerance applies to circles and arcs. The Run-out value reflects the form of the feature as well as the eccentricity of the feature to the reference point.



### Total Run-out

Total Run-out is a three-dimensional tolerance zone defined by the minimum and maximum points of a feature surface to a reference axis of rotation. This tolerance applies to cylinders and cones. The Run-out value reflects the form of the feature as well as the eccentricity of the feature to the reference axis.

## Entering Tolerances

If the feature is not already selected, select the feature you wish to tolerance from the Features list or from the Schematic window.

Next, right click with the mouse and select Tolerances from the options.

The Feature Tolerances dialog box will display the feature's bilateral tolerances. Bilateral tolerances are the basic position and size characteristics of the feature.

You may enter values in the Nominal and tolerance columns. These cells will normally have a white background. However, if the characteristic is out of tolerance, the cell will have a red background. The values in the other columns are computed and cannot be edited.


### Entering Form Tolerances

Form tolerances include circularity, flatness, and straightness.

First, if the feature is not already selected, select the feature you wish to tolerance from the Schematic window.

Next, you will need to bring up the appropriate Form Tolerance dialog. This can be achieved by either clicking on the desired form tolerance button from the Tolerance Tool Bar or by selecting the desired form tolerance from the Tolerance menu from the Features Context Menu.

The following is a Form Dialog (Circularity):



Use the tab key or the mouse to maneuver around the dialog.

- Feature Type – Displays the feature being tolerated.



- Actual – Displays the measured values.
- Tolerance – The tolerance zone.
- Deviation – Displays the difference between the Actual and the Nominal.


If you are applying the tolerance to a group of circles, the Actual value will remain blank. If multiple values already exist, question marks, “???”, will appear in the tolerance box.

### Entering True Position Tolerances

True Position tolerances include RFS, MMC, and LMC.

After you select the feature(s) you wish to tolerance, select Tolerances... from the Features Context Menu.

Select the appropriate positional tolerance from the tabs in the Tolerance Dialog Box.




For TP MMC and TP LMC a bonus will be calculated and applied during the evaluation.

The following is the dialog for TP MMC for a single feature:

Use the tab key or the mouse to maneuver around the dialog.

- Icons – Use the icons on the right to specify if the feature is a hole or boss.
- Actual – Displays the measured values.
- Nominal – Displays the nominal value. This number must be entered.
- Deviation – Displays the difference between the Actual and the Nominal.
- Deviation from Nominal – The true location from nominal based on a diametrical zone.
- Tolerance – The tolerance zone.
- Bonus – An increase in the tolerance based on the feature departing from its MMC size.
- Effective (Tolerance + Bonus) – The effective tolerance zone considering the bonus.
- Deviation from effective – How far off the hole or boss is from the Effective Tolerance Zone.

In addition to its LMC or MMC bonus, a feature can have a datum bonus applied to its tolerance. If the datum of a feature has a LMC or MMC tolerance, the bonus from the datum can also be added to the effective tolerance of the feature. When you click on the Datum Bonus icon, the following window appears:




Fill in information as you did for the LMC and MMC scenarios above. When you click **OK** the bonus will automatically apply to the feature tolerance.

### Tolerances the require Reference Features

Some ANSI Y14.5 tolerances, including angularity, concentricity, perpendicularity, and parallelism, are dependent upon a datum feature. For these tolerances, an additional combo box will appear allowing you to select the reference feature.

Following is an example for concentricity using circle 3 as the reference feature.



You can use the tab key or the mouse to maneuver around the dialog.

- Feature Type – Displays the feature type being tolerated. If you have selected multiple feature types, use the pull-down box to switch feature types.
- Reference Feature – Displays the feature being referenced to determine the tolerance.
- Actual – Displays the measured value.
- Tolerance – Displays the nominal value. This number must be entered.
- Deviation – Displays the difference between the Actual and Tolerance.

## Chapter 12 Exporting Data

Each measured feature type has six or more exportable properties. A distance as seen below has seven properties. In addition, you can export the Nominal & Tolerances and Labels for each property. InSpec allows you to select individual export properties for each feature and save.

### Feature Exports

The Feature Exports dialog boxes have been designed to be simple to use and understand.

Setting export properties for features can be performed on an individual feature or a group of features. To setup the properties to be exported for a single feature, right click on a feature and select Exports from the Features List context menu.

A dialog box similar to the one below will be displayed with the feature name at the top.



- Export Nominals & Tolerances – This option will automatically include tolerance information if available for each of the selected properties.
- Export with Label – This option allows the user to include labels with exported data. The default label is the feature name followed by the property, the whole label is in quotes, i.e. "Circle 1: Center X".
- Export Property – Click on the check boxes to specify which properties are to be exported.
- Label – These cells are used to create custom labels for each export property. If Export Labels is checked and the Export Property is checked, InSpec will check for and export the custom label with the property's value. If a custom label is not entered, the default label will be exported.

### Multiple Feature Exports

Export properties can be set for a block of features. After selecting multiple features in the Features list, right click on a selected feature and select Exports. This will display the Multiple Selection dialog box.



There are two differences between the individual and multiple selection dialog boxes. First, the dialog box header changes to indicate that you have selected multiple features.

Second, InSpec displays a drop down list under Feature Type when a group of features with different feature types has been selected. InSpec separates the feature types for you, so you can assign the appropriate export properties.

For example, you may have a program with a mixture of points, lines, and circles, but you are only interested in the diameters of the holes. You can select all the features in you feature list (Ctrl+A), right click and select Exports, choose Circle from the Feature Type drop down menu, and then check the Diameter box. Now all of the diameters are ready to be exported.

## Export Configuration

InSpec allows you to manually or automatically export data. To export automatically, please see the Export File Parameters and the Serial Export Parameters sections in Chapter 13.

To manually send data to a file or port, select **Export** under the **File** menu.



## Setting the Export Destination

With the manual export, you can send data to a file or a data port. Use the File or Serial Port radio buttons to make your selection.

When exporting to a file, you must enter a data file name and location. Use the button with three dots to browse through directories. Check the **Append to Existing File** if you want to add data to the end of an existing file. If the box is not checked, InSpec will replace existing data with new data.

When exporting to a Serial Port, the Configure Port button will become active and allow you to adjust port settings.

## Formatting

- **Run Separators** – This toggle enables :BEGIN and :END markers to be included with the export data.
- **Unicode Text Encoding** – If you want to export text, prompts, or labels that contain Unicode characters, you must check this box. This setting will be helpful if you are not using the US-English character set.
- **Compatible with InSpec 1.XX** – The export order of some tolerance fields has changed since InSpec Version 1.XX. Check this option to use the order used in 1.XX. The different orders are shown in Appendix A.

## Delimiter

- **Field Delimiter** – Select the separation character to go between feature data. (Line 1 data [,] Arc 2 data [,] Circle 3 data [,] ...)
- **Record Delimiter** – Select the separation character to go between feature property data. (Arc 2:Center X [,] Arc 2:Center Y [,] Arc 2;Diameter [,] ...)

For automatic reporting using **Playback Options** ... under the **Tools** menu, refer to the section on Automated Reporting for more information.

## Output Format

The different types of tolerances have different fields to export. The typical order for data is [Label,] Actual, [Nominal, PlusTol, MinusTol, DevNom, DevTol].

The Label is optional and must be checked in the Feature Exports dialog to be exported. Exporting the nominal and tolerances is also an option in the Feature Exports dialog. Samples are shown in Appendix A.

## Part Separators

The part separator is a special feature type used to format your data. It exports a Carriage Return and Line Feed (CR/LF) when it is reached in a program. This can help manage exported data for a program that measures multiple parts. Select **Insert** from the **Feature** menu, and then select **Part Separator** to insert a new Part Separator feature into the part program.

The part separator is commonly used when multiple parts are being measured in a single part program. To see why this is useful, let's imagine that 5 paper clips are placed in a row in a fixture. Measure some arcs and distances on the first paper clip. Set the radii and distances to export using comma or tab delimiters. Use Translate to make 4 copies of the first clip. Now export the results to a file. When exported, the data for the five clips would be strung together on a single line. This can be difficult to handle.

By adding a part separator at the end of the measurements for each clip, the data for each part will be on a separate line. With each part's data on a separate line, it is easier to import the data into SPC and other software.

## Chapter 13 Playback Options

InSpec does more than measure parts and display data. It provides options to automatically print, save, and transmit data. Tool and tolerance “failure” modes can also be activated. These tasks and settings can be saved with each program.

These options are accessed from **Playback Options...** under the **Tools** menu.



### Export File Parameters

After properties of the features have been selected for exporting, you are ready to send the data to a file. The export file will be a text file (\*.txt).

Manual exporting can be performed by selecting **Export** from the **File** menu.

Automatic Exporting can be performed by selected **Playback Options ...** from the **Tools** menu. The dialog box above will appear. Automatic Exporting appends data to the end of the designated file every time the program is run.

- **Export**– Use the radio buttons to select when you want the data exported, “Disabled” (off, no export), “During Run”, “After Run”, and “After Run Confirm”. “During Run” sends data as each feature is measured. This can help when an SPC program is monitoring the data file. “After Run” waits until all features are measured, and “Confirm” will prompt the user before sending data.
- **File** – Enter a data file name and location. Use the button with three dots to browse through directories. If an existing file is selected, data is automatically appended to the end of file.

### Formatting

- **Run Separators** – This toggle enables “:BEGIN” and “:END” markers to be included with the export data.
- **Unicode Text Encoding** – If you want to export text, prompts, or labels that contain Unicode characters, you must check this box. This setting will be helpful if you are not using the US-English character set.
- **Compatible with InSpec 1.xx** – The export order of some tolerance fields has changed since

InSpec Version 1.xx. Check this option to use the order used in 1.xx. Refer to the appendix for examples of 1.xx and 2.xx outputs.

### Delimiter

- Field Delimiter – Select the separation character to go between feature data. (Line 1 data [,] Arc 2 data [,] Circle 3 data [,] ...)
- Record Delimiter – Select the separation character to go between feature property data. (Arc 2:Center X [,] Arc 2:Center Y [,] Arc 2:Diameter [,] ...)


The export delimiter types set in this dialog are applied for both the manual and automatic export.

## Serial Export Parameters

Exporting data to a serial port requires the same options as described for exporting to a file.



However there is an additional button to configure the serial port settings.



## Printing a Report

Printing can be automated at the end of each program or at any time by selecting Print from the File menu. There are four options regarding which data to print: All Features, Toleranced Features, Out of Tolerance Features, or Features marked for Export.

Each report has a header that gives the program title, date and time, units, and column headings. The page number will be printed at the bottom of the page.



**Print all Features** will print all of the features in the following format:

Feature	Actual	Nominal	Plus (+)	Minus (-)	Dev/Non	Out/Tol
Program: Untitled Date: Wed Jul 11 2001 Time: 15:02:07						
Units: in, dec deg						
Point 1	[MC3]					
Location X	4.42326	4.42326			0.0000	
Location Y	4.81317	4.81317			0.0000	
Location Z	0.00000	0.00000			0.0000	
Line 2	[MC3]					
Location X	3.53423	3.53423			0.0000	
Location Y	4.35616	4.35616			0.0000	
Length XY	1.60711	1.60711			0.0000	
Direction	3.4292	3.4292			0.0000	
Straightness	0.02380					
Line 3	[MC3]					
Location X	0.25342	0.25342			0.0000	
Location Y	3.78859	3.78859			0.0000	
Length XY	1.74427	1.74427			0.0000	
Direction	-59.0636	-59.0636			0.0000	
Straightness	0.10773					
Point 4	[MC3]					
Location X	0.26465	0.26465			0.0000	
Location Y	4.53582	4.53582			0.0000	
Location Z	0.00000	0.00000			0.0000	
System 5	[MC3]					
Origin X	4.42326	4.42326			0.0000	
Origin Y	4.81317	4.81317			0.0000	
Skew	-0.0636	-0.0636			0.0000	
Angle 6	[System 5]					
Vertex X	0.25680	0.25680	0.01000	0.01000	0.01173	0.01173
Vertex Y	-0.27551	-0.26324			-0.01327	
Angle	59.0000	59.0000	2.0000	2.0000	0.0000	
Angle 7	[System 5]					
Vertex X	0.25680	0.25680	0.01000	0.01000	0.01266	0.01266
Vertex Y	-0.27551	-0.24866			-0.02685	
Angle	59.0000	59.0000	2.0000	2.0000	0.0000	
Angle 8	[System 5]					
Vertex X	0.25211	0.25680	0.01000	0.01000	0.01179	0.01179
Vertex Y	-1.26454	-1.19080			-0.07374	
Angle	59.0000	59.0000	2.0000	2.0000	0.0000	
Angle 9	[System 5]					
Vertex X	0.25211	0.25680	0.01000	0.01000	0.08231	
Vertex Y	-1.26455	-1.61881			-0.35426	
Angle	59.0000	59.0000	2.0000	2.0000	0.0000	

Selecting **Print toleranced Features** will only print those features that have toleranced characteristics in the following format:



Program: Untitled		Date: Wed Jul 11 2018					Time: 19:01:09
Units: in, dec deg							
Feature	Actual	Nominal	Plus (+)	Minus (-)	Dev/Min	Out/Tol	
Angle 5	[System 5]	0.25000	0.01000	0.01000	0.02173	0.01173	
Vertex X	0.17173	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle	50.0000	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle 7	[System 5]	0.25000	0.01000	0.01000	0.02166	0.01166	
Vertex X	0.17266	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle	50.0000	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle 6	[System 5]	0.25000	0.01000	0.01000	0.02179	0.01179	
Vertex X	0.16179	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle	50.0000	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle 9	[System 5]	0.25000	0.01000	0.01000	0.02231	0.01231	
Vertex X	0.15231	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle	50.0000	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle 18	[System 5]	0.25000	0.01000	0.01000	0.01020	0.00020	
Vertex X	0.16020	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle	50.0000	0.00000	0.00000	0.00000	0.00000	0.00000	
Point 24	[System 5]	4.09207	0.01000	0.01000	0.00000	0.00000	
Location X	4.08207	0.00000	0.00000	0.00000	0.00000	0.00000	
Point 25	[System 5]	4.99740	0.01000	0.01000	0.00000	0.00000	
Location X	4.98740	0.00000	0.00000	0.00000	0.00000	0.00000	
Point 26	[System 5]	5.90264	0.01000	0.01000	0.00000	0.00000	
Location X	5.89264	0.00000	0.00000	0.00000	0.00000	0.00000	
Point 27	[System 5]	6.80690	0.01000	0.01000	0.00000	0.00000	
Location X	6.79690	0.00000	0.00000	0.00000	0.00000	0.00000	

Selecting **Print out of tolerance Features** will only print those features that are out of tolerance, in the following format:

Program: Untitled		Date: Wed Jul 11 2018					Time: 18:59:46
Units: in, dec deg							
Feature	Actual	Nominal	Plus (+)	Minus (-)	Dev/Min	Out/Tol	
Angle 5	[System 5]	0.25000	0.01000	0.01000	0.02173	0.01173	
Vertex X	0.17173	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle 7	[System 5]	0.25000	0.01000	0.01000	0.02166	0.01166	
Vertex X	0.17266	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle 6	[System 5]	0.25000	0.01000	0.01000	0.02179	0.01179	
Vertex X	0.16179	0.00000	0.00000	0.00000	0.00000	0.00000	
Angle 18	[System 5]	0.25000	0.01000	0.01000	0.01020	0.00020	
Vertex X	0.16020	0.00000	0.00000	0.00000	0.00000	0.00000	

The **Print Exports** option will use the same format. It will only print feature properties that are marked for export.

Another Print option under the File menu is Print Schematic. This option will print the features (and Tags if present) in the Schematic Window. It is useful to display tags and print the Schematic to help document inspection procedures.


## Handling Failures

The **Tool Failure Mode** and **Tolerance Failure Mode** each provide three options: stop, wait for the user, and continue. These options can save you time measuring parts.

For instance, use the “skip and continue” tool failure mode if you need to leave the machine unattended. InSpec will run the entire program and allow you to fix “failed” tools when you return. InSpec will check to see if the feature is needed to create a system. If it is, the InSpec will automatically pause and wait for the user.

If the user will be monitoring the system while running the program, it is best to use the “pause and wait for user” tool fail mode.

The “stop the program” tolerance failure mode can be used to stop after the first out of tolerance measurement. The operator can go to the next part without spending additional time on a rejected part.



## Chapter 14 Advanced Features

InSpec for Windows includes advanced features that allow parts to be measured without user input, reports to be generated automatically, and displayed measurements to be customized.

### Stored Features

InSpec software allows features to be stored in memory. Once stored, they can be used in other programs. Stored features can be used to save the position of a fixture. The position of the fixture can then be used to start your part program. With a known initial coordinate system, the part program will run automatically after an operator presses the run button.

Storing a Feature is very simple. Create a system from measured features. Select the system that you want to store and choose Store Feature from the Features Context Menu. The following dialog will appear:



Check the box next to *Store As* and enter a unique name. The name can be any combination of letters and numbers. Unless the *Save Permanently* box is checked, the feature will only be saved for the current session of InSpec and will be lost when the software is closed. If saved permanently, the feature will remain until manually removed via Tools – Stored Features.


### Using a Stored Feature

Once a feature has been stored, it can be recalled as an input for another feature.

- Select a feature icon such as a System.

- Select the Recall icon .

The following Dialog will appear with a list of available stored features.



- Select a stored feature with a double click on the stored feature's name or with one click on the stored feature's name and a second on OK.

In most cases, Stored features are used as a coordinate system at the beginning of a program. For example, suppose you have the corner of a fixture saved as an external angle called "FX1." The first step in your program might be to set a system origin (X, Y, and Z) to a Stored feature. By doing so, you automatically have your initial coordinate system measured when you load the program.


### What Happens During the Run Mode?

In the run mode, when InSpec encounters a feature that uses a stored feature as input, InSpec checks the memory for a measured feature with that name. If the feature exists, InSpec simply uses that stored feature's data to create the new feature. If the Stored feature is not found in

memory, InSpec will not run the program. Therefore it is important to permanently save features that are used often.

### Clearing Stored Features from memory

If you want to clear existing Stored Features from memory, from the Tools Menu choose *Stored Features*. The following dialog will appear:



You will have the options to Close the dialog box, delete a stored feature, or Delete all of the stored features. RefSys will appear in the list and cannot be removed.

### REFSYS Home Position

REFSYS is a stored feature with an origin at the lower front left corner of the stage volume and skew of the X axis. This entry will always be present in the Recall Feature dialog box.

REFSYS can be used to make programs run without any operator inputs. This works best with a fixture that is permanently attached to the stage or a fixture that is removable but is always attached in the same location. A fixture may be as simple as an “L” bracket bolted or glued to the front left corner of the stage. The key to using REFSYS is that the location of a part in a fixture on the stage will always be the same relative to the home position.

To use REFSYS in a program, start a new program with a system and recall REFSYS from the list of stored features. Then begin a part program.

Start with features that define the part coordinate system, set a system skew and origin for the part and then add a few other features. When you run the program, InSpec should drive to the features and make the measurements without any user input.

REFSYS is also useful for taking quick measurements on a part that is not fixtured. You can rerun the program while the part is in the same location. You can use REFSYS in conjunction with cycle to check repeatability of focus points or edge tools on a particular material or surface.

### Cycling a Program

The Cycle option under the Playback Menu is similar to the Run playback icon. However, Cycle will continue to rerun a program for a fixed number of runs or indefinitely. This can be useful for running several of the same part in a single fixture, gathering repeatability data when used with auto-export, and for demonstrating to customers and suppliers.

After writing a program, simply select Cycle from the Program Menu. Select the number of time to run the program, or select indefinite to run the program continuously. At any, time the program may be interrupted with the Stop button. Programs beginning with a stored feature or REFSYS will cycle without any user input. Other programs will require the user to manually measure the features required to establish the initial system at the beginning of each cycle.



## Center Tools on Measurements

This function automatically moves all of the search zones in the program so that they are centered on the measured data. This makes the best use of the search area and minimizes the chance that a tool will fail on future parts. This also allows you to use smaller search zones and cut down on processing time. To access this function go to the Tools menu and choose 'Center Tools on Measurements'.

## Importing CAD Files

InSpec for Windows is capable of importing DXF, Excellon, IGES, and Gerber format files. These formats are the most popular CAD file types and most CAD programs can export in one of these formats. (Note: Import translators are optional and may not be included. Contact your local dealer for assistance.)

Features in the CAD files are loaded and converted to features in an InSpec file. InSpec allows the operator to create an origin from the imported unmeasured features and then “convert to initial system.” After setting appropriate lighting and magnification, InSpec will “convert import inputs” to automatically create tools for all of the features. In less than a minute you can create a program.

### Importing a DXF File

The import process is very similar for all file types. Here is an example DXF file from the sample part in the InSpec for Windows directory.

The Import process begins with opening a CAD file. After the user specifies conversion units, the features in the file are converted to InSpec features. The operator creates an initial coordinate system, and then sets the zoom and lighting. Then the part is ready to be measured.

To begin, select Import from the File menu.

You will be prompted to enter the name of the import file. Near the bottom of the dialog box you can select the file type, DXF, Excellon, etc., you are about to import.



Select the file you would like to import and click on Open.

After you have selected the import file, you will be prompted to select the scale factor of the CAD file and the linear and angular units. The default dimension factor is one, i.e. a one to one scale factor. The default angular units are degrees.



Select the correct units for the CAD file, and click on OK.

At this point, InSpec for Windows will convert each of the CAD file features into InSpec features. A list of the features will be displayed and a diagram of the part will be drawn in the schematic window.

The next step in the conversion process is to set up an initial system for the part using features from the CAD file. In many cases, you will intersect two lines to create a point. The point will become system origin (0,0,0) and one of the lines will be used for the system skew alignment.

### Create a system from the imported file

In this example, create a point at the intersection of the left vertical line and the bottom horizontal line. Set the X-Y-Z Origin on the point. Set the Skew to the bottom horizontal line. The new system will be used as the initial system for the program.

**After creating the system, select the Continue button in the Import – System Construction message box.**



InSpec will make copies of the features used to create the initial system, in this case two lines, and a point, and place them at the beginning of the program list. Line 1, Line 2, and Point 1 in this example create the new initial system, System 2.

### Set the light and zoom settings for your part.

The light and zoom you choose will be used for all of the CAD features after they are converted in the next step. After you run the program, you will be able to change the lighting and zoom for individual points.

InSpec will create the individual tools for each feature. If you look at the current inputs of the CAD features, you will see "IMPORT" instead of a Best Edge, First Edge, or Feature Scan tool. The Tool Create step will add 3 Best Edge points to each CAD line and 4 Best edge points to each circle or arc. If the CAD feature can fit in the field of view, the appropriate Feature Scan tool will be used.



After selecting Finish, the tools will be applied to the features. The features will not have data indicating that they are unmeasured. The file conversion is complete and you can now run the program.

At this point the program is just like any other that you have created. You can add and delete features. You can edit and save the program. You can verify that the program has been imported properly by viewing tolerances. The tolerance dialog box will show the nominal locations of features. These numbers should match the number in the DXF file.

### Run the program.

To playback the program, click on the Run button.

You will be prompted to measure the features used to create the initial coordinate system. It is helpful to turn on tags for initial features to help the user locate the initial features.

After measuring the initial features, InSpec will be able to create the initial system and measure the other features automatically. It is important to watch the program the first time through to make sure that the lighting, tool sizes, and zoom are appropriate. Adjust tools, magnification, and lighting as needed.

## Exporting DXF Files

InSpec for Windows currently allows the user to export DXF format files. DXF is a popular CAD file type that most CAD programs can accept.

The Export process begins by measuring a part with InSpec. Then, select Export DXF from the File menu. You will be prompted to enter the name of the export file.



Enter a file name at the prompt and click on Save. By default, InSpec will add the DXF extension to the file name.

The coordinate system can be selected via a pull down menu which includes all the systems in the program. If you are bringing the DXF into a CAD or bestfit software, the system which is chosen from this menu will effect the feature coordinates.

## New Program Defaults

Program defaults set parameters for NEW programs. The tabs at the top of the window divide four sets of parameters: display, export, run failures, and temperature compensation.

### Display Defaults

The system type, linear, and angular parameters are set in the display tab. Standard rounding is used when displaying data. The Number of Digits refers to the number of places to the right of the decimal point.



## Export Defaults


The export delimiter types set in this dialog are applied for both the manual and automatic export.

### Formatting

- **Run Separators** – This toggle enables :BEGIN and :END markers to be included with the export data.
- **Unicode Text Encoding** – If you want to export text, prompts, or labels that contain Unicode characters, you must check this box. This setting will be helpful if you are not using the US-English character set.
- **Compatible with InSpec 1.x** – The export order of some tolerance fields has changed since InSpec Version 1.x. Check this option to use the order used in 1.XX. The different orders are shown in the appendix.

### Delimiter


- **Field Delimiter** – Select the separation character to go between feature data.
- **Record Delimiter** – Select the separation character to go between feature property data.



## Run Failures


Run Failures sets the conditions for stopping a program. Depending on the application and program, the operator may want the system to run completely through the program or stop and wait for the operator if a tool fails or a feature is out of tolerance. With long programs, it is more convenient to allow the program to run to the end than to sit and watch for problems. The operator can start a program and return after all features have been processed. Features that were out of tolerance or unmeasured can then be edited, updated, or fixed when the operator returns. In other cases, it may be more convenient to have the operator monitor a long program because tools can be immediately fixed. Or if one dimension is out of tolerance, then the operator can stop the program, discard the bad part, and start on the next part.






### Temperature Compensation

Temperature compensation can provide the additional accuracy required for a tight tolerance or be removed to provide a simplified interface. The settings allow a temperature feature to be added to the beginning of each program and to request the temperature at the beginning of each run. Consider using temperature compensation for large parts and very long programs with thousands of features. The basic premise of any temperature compensation is that the machine, the room, and the part have settled to equilibrium. If there are large temperature swings ( $> \pm 2^\circ \text{F}$ ), then the temperature variation will have more of an effect than the compensation.



### Construction Defaults

Because Micro-Vu measurement systems are used to measure everything from precision ball bearings and computer chips to rubber hoses and coat hangers, we have tried to make the software powerful yet simple. The Construction Defaults give the operator a means to customize some of the functionality. The distance between two circles can be the minimum, center-to-center, or maximum distance. The same options are available for a circle to a line or a circle to a point. There are two options for a line bisecting two lines, a line along the bisecting angle and its perpendicular.



### Configure Summary

The characteristics in the Summary Window and printouts are controlled in Configure Summary. These settings are saved with each program. As shown earlier in the manual, the display of individual characteristics for each feature type may be turned on and off. Select the feature type from the tabs at the top of the dialog. Then check the boxes of the characteristics you would like displayed.



### Configure Audio


InSpec gives you the option to change its audio settings. If you are using the joystick and are far away from the computer, you can run the sound through external speakers and increase the volume.



## Platen

The platen is an optional accessory that raises and lowers a large piece of glass above the stage glass. This is used to sandwich thin parts and keep them in place and flat. The platen for a Quantum uses an air cylinder. The platen for an Excel is motorized.

Use the F8 hot key or the Open/Close Platen option under the Machine menu to operate the platen.



When the platen is opened, InSpec will automatically drive the machine so that the camera is at the back of the stage. Then the platen will open. While the platen is open, stage controls will be disabled to prevent the camera from being driven into the platen.



Use the Close button in the pop up dialog or the F8 hokey to close the platen. InSpec will drive the camera back to its original position after the platen is closed.


## Chapter 14 Advanced Features

InSpec for Windows includes advanced features that allow parts to be measured without user input, reports to be generated automatically, and displayed measurements to be customized.

### Stored Features

InSpec software allows features to be stored in memory. Once stored, they can be used in other programs. Stored features can be used to save the position of a fixture. The position of the fixture can then be used to start your part program. With a known initial coordinate system, the part program will run automatically after an operator presses the run button.

Storing a Feature is very simple. Create a system from measured features. Select the system that you want to store and choose Store Feature from the Features Context Menu. The following dialog will appear:



Check the box next to *Store As* and enter a unique name. The name can be any combination of letters and numbers. Unless the *Save Permanently* box is checked, the feature will only be saved for the current session of InSpec and will be lost when the software is closed. If saved permanently, the feature will remain until manually removed via Tools – Stored Features.

### Using a Stored Feature

Once a feature has been stored, it can be recalled as an input for another feature.

- Select a feature icon such as a System.

- Select the Recall icon .

The following Dialog will appear with a list of available stored features.



- Select a stored feature with a double click on the stored feature's name or with one click on the stored feature's name and a second on OK.

In most cases, Stored features are used as a coordinate system at the beginning of a program. For example, suppose you have the corner of a fixture saved as an external angle called "FX1." The first step in your program might be to set a system origin (X, Y, and Z) to a Stored feature. By doing so, you automatically have your initial coordinate system measured when you load the program.


### What Happens During the Run Mode?

In the run mode, when InSpec encounters a feature that uses a stored feature as input, InSpec checks the memory for a measured feature with that name. If the feature exists, InSpec simply uses that stored feature's data to create the new feature. If the Stored feature is not found in

memory, InSpec will not run the program. Therefore it is important to permanently save features that are used often.

### Clearing Stored Features from memory

If you want to clear existing Stored Features from memory, from the Tools Menu choose *Stored Features*. The following dialog will appear:



You will have the options to Close the dialog box, delete a stored feature, or Delete all of the stored features. RefSys will appear in the list and cannot be removed.

### REFSYS Home Position

REFSYS is a stored feature with an origin at the lower front left corner of the stage volume and skew of the X axis. This entry will always be present in the Recall Feature dialog box.

REFSYS can be used to make programs run without any operator inputs. This works best with a fixture that is permanently attached to the stage or a fixture that is removable but is always attached in the same location. A fixture may be as simple as an “L” bracket bolted or glued to the front left corner of the stage. The key to using REFSYS is that the location of a part in a fixture on the stage will always be the same relative to the home position.

To use REFSYS in a program, start a new program with a system and recall REFSYS from the list of stored features. Then begin a part program.

Start with features that define the part coordinate system, set a system skew and origin for the part and then add a few other features. When you run the program, InSpec should drive to the features and make the measurements without any user input.

REFSYS is also useful for taking quick measurements on a part that is not fixtured. You can rerun the program while the part is in the same location. You can use REFSYS in conjunction with cycle to check repeatability of focus points or edge tools on a particular material or surface.

### Cycling a Program

The Cycle option under the Playback Menu is similar to the Run playback icon. However, Cycle will continue to rerun a program for a fixed number of runs or indefinitely. This can be useful for running several of the same part in a single fixture, gathering repeatability data when used with auto-export, and for demonstrating to customers and suppliers.

After writing a program, simply select Cycle from the Program Menu. Select the number of time to run the program, or select indefinite to run the program continuously. At any, time the program may be interrupted with the Stop button. Programs beginning with a stored feature or REFSYS will cycle without any user input. Other programs will require the user to manually measure the features required to establish the initial system at the beginning of each cycle.



## Center Tools on Measurements

This function automatically moves all of the search zones in the program so that they are centered on the measured data. This makes the best use of the search area and minimizes the chance that a tool will fail on future parts. This also allows you to use smaller search zones and cut down on processing time. To access this function go to the Tools menu and choose 'Center Tools on Measurements'.

## Importing CAD Files

InSpec for Windows is capable of importing DXF, Excellon, IGES, and Gerber format files. These formats are the most popular CAD file types and most CAD programs can export in one of these formats. (Note: Import translators are optional and may not be included. Contact your local dealer for assistance.)

Features in the CAD files are loaded and converted to features in an InSpec file. InSpec allows the operator to create an origin from the imported unmeasured features and then “convert to initial system.” After setting appropriate lighting and magnification, InSpec will “convert import inputs” to automatically create tools for all of the features. In less than a minute you can create a program.

### Importing a DXF File

The import process is very similar for all file types. Here is an example DXF file from the sample part in the InSpec for Windows directory.

The Import process begins with opening a CAD file. After the user specifies conversion units, the features in the file are converted to InSpec features. The operator creates an initial coordinate system, and then sets the zoom and lighting. Then the part is ready to be measured.

To begin, select Import from the File menu.

You will be prompted to enter the name of the import file. Near the bottom of the dialog box you can select the file type, DXF, Excellon, etc., you are about to import.



Select the file you would like to import and click on Open.

After you have selected the import file, you will be prompted to select the scale factor of the CAD file and the linear and angular units. The default dimension factor is one, i.e. a one to one scale factor. The default angular units are degrees.



Select the correct units for the CAD file, and click on OK.

At this point, InSpec for Windows will convert each of the CAD file features into InSpec features. A list of the features will be displayed and a diagram of the part will be drawn in the schematic window.

The next step in the conversion process is to set up an initial system for the part using features from the CAD file. In many cases, you will intersect two lines to create a point. The point will become system origin (0,0,0) and one of the lines will be used for the system skew alignment.

### Create a system from the imported file

In this example, create a point at the intersection of the left vertical line and the bottom horizontal line. Set the X-Y-Z Origin on the point. Set the Skew to the bottom horizontal line. The new system will be used as the initial system for the program.

**After creating the system, select the Continue button in the Import – System Construction message box.**



InSpec will make copies of the features used to create the initial system, in this case two lines, and a point, and place them at the beginning of the program list. Line 1, Line 2, and Point 1 in this example create the new initial system, System 2.

### Set the light and zoom settings for your part.

The light and zoom you choose will be used for all of the CAD features after they are converted in the next step. After you run the program, you will be able to change the lighting and zoom for individual points.

InSpec will create the individual tools for each feature. If you look at the current inputs of the CAD features, you will see "IMPORT" instead of a Best Edge, First Edge, or Feature Scan tool. The Tool Create step will add 3 Best Edge points to each CAD line and 4 Best edge points to each circle or arc. If the CAD feature can fit in the field of view, the appropriate Feature Scan tool will be used.



After selecting Finish, the tools will be applied to the features. The features will not have data indicating that they are unmeasured. The file conversion is complete and you can now run the program.

At this point the program is just like any other that you have created. You can add and delete features. You can edit and save the program. You can verify that the program has been imported properly by viewing tolerances. The tolerance dialog box will show the nominal locations of features. These numbers should match the number in the DXF file.

### Run the program.

To playback the program, click on the Run button.

You will be prompted to measure the features used to create the initial coordinate system. It is helpful to turn on tags for initial features to help the user locate the initial features.

After measuring the initial features, InSpec will be able to create the initial system and measure the other features automatically. It is important to watch the program the first time through to make sure that the lighting, tool sizes, and zoom are appropriate. Adjust tools, magnification, and lighting as needed.

## Exporting DXF Files

InSpec for Windows currently allows the user to export DXF format files. DXF is a popular CAD file type that most CAD programs can accept.

The Export process begins by measuring a part with InSpec. Then, select Export DXF from the File menu. You will be prompted to enter the name of the export file.



Enter a file name at the prompt and click on Save. By default, InSpec will add the DXF extension to the file name.


The coordinate system can be selected via a pull down menu which includes all the systems in the program. If you are bringing the DXF into a CAD or bestfit software, the system which is chosen from this menu will effect the feature coordinates.

## New Program Defaults

Program defaults set parameters for NEW programs. The tabs at the top of the window divide four sets of parameters: display, export, run failures, and temperature compensation.

### Display Defaults

The system type, linear, and angular parameters are set in the display tab. Standard rounding is used when displaying data. The Number of Digits refers to the number of places to the right of the decimal point.





## Export Defaults


The export delimiter types set in this dialog are applied for both the manual and automatic export.

### Formatting

- **Run Separators** – This toggle enables :BEGIN and :END markers to be included with the export data.
- **Unicode Text Encoding** – If you want to export text, prompts, or labels that contain Unicode characters, you must check this box. This setting will be helpful if you are not using the US-English character set.
- **Compatible with InSpec 1.x** – The export order of some tolerance fields has changed since InSpec Version 1.x. Check this option to use the order used in 1.XX. The different orders are shown in the appendix.


### Delimiter

- **Field Delimiter** – Select the separation character to go between feature data.
- **Record Delimiter** – Select the separation character to go between feature property data.




## Run Failures

Run Failures sets the conditions for stopping a program. Depending on the application and program, the operator may want the system to run completely through the program or stop and wait for the operator if a tool fails or a feature is out of tolerance. With long programs, it is more convenient to allow the program to run to the end than to sit and watch for problems. The operator can start a program and return after all features have been processed. Features that were out of tolerance or unmeasured can then be edited, updated, or fixed when the operator returns. In other cases, it may be more convenient to have the operator monitor a long program because tools can be immediately fixed. Or if one dimension is out of tolerance, then the operator can stop the program, discard the bad part, and start on the next part.



### Temperature Compensation

Temperature compensation can provide the additional accuracy required for a tight tolerance or be removed to provide a simplified interface. The settings allow a temperature feature to be added to the beginning of each program and to request the temperature at the beginning of each run. Consider using temperature compensation for large parts and very long programs with thousands of features. The basic premise of any temperature compensation is that the machine, the room, and the part have settled to equilibrium. If there are large temperature swings ( $>+/-2^{\circ}\text{F}$ ), then the temperature variation will have more of an effect than the compensation.



### Construction Defaults

Because Micro-Vu measurement systems are used to measure everything from precision ball bearings and computer chips to rubber hoses and coat hangers, we have tried to make the software powerful yet simple. The Construction Defaults give the operator a means to customize some of the functionality. The distance between two circles can be the minimum, center-to-center, or maximum distance. The same options are available for a circle to a line or a circle to a point. There are two options for a line bisecting two lines, a line along the bisecting angle and its perpendicular.